



An overgrown Cattle Dip Vat.





An overgrown Cattle Dip Vat.





An overgrown Cattle Dip Vat.





View of the trench of  
a Cattle Dip Vat





**A view of the ramp area of a  
Cattle Dip Vat.**





**A ramp area of a  
Cattle Dip Vat.**



A photograph of a heavily overgrown area in a forest. The scene is dominated by dense, green vegetation, including various shrubs and small trees. Several large, thick tree trunks are visible, some with rough, textured bark. In the background, a dark, rectangular structure, likely a cattle dip vat, is partially obscured by the thick brush and branches. The ground is covered with fallen leaves and twigs. The overall impression is one of a neglected and overgrown site.

**An overgrown Cattle  
Dip Vat.**



A photograph of a dense, overgrown area. In the foreground, a large, textured tree trunk stands on the left. The ground is covered with dry leaves and sparse green vegetation. In the background, a concrete structure, likely a ramp or part of a vat, is partially visible through the thick foliage. The scene is brightly lit, suggesting a sunny day.

**The ramp  
area of a  
Cattle Dip Vat.**



A photograph showing a concrete cattle dip vat almost completely hidden by a dense thicket of trees and branches. The scene is overgrown with various green plants and fallen sticks, making the structure difficult to see. The text is overlaid in the bottom left corner.

**A Cattle Dip Vat  
obscured by plants  
and debris.**





**A Cattle Dip Vat  
obscured by plants  
and debris.**



A photograph showing a concrete structure with a rectangular opening. The opening reveals a dark, narrow trench filled with various pieces of debris, including plastic bags and other waste. The concrete walls are weathered and have some vines growing on them. Green leaves and branches are visible in the foreground and background, partially obscuring the view.

**A view of the debris  
filled trench of a  
Cattle Dip Vat.**



A photograph showing a narrow, deep trench between two concrete walls. The trench is filled with a thick layer of dark, wet debris, including sticks, twigs, and leaves. A bright green plastic bucket is visible in the middle of the debris. The concrete walls are weathered and have some green moss or algae growing on them. The background shows more of the trench and some green foliage.

**A view of the debris  
filled trench of a  
Cattle Dip Vat.**






**An overgrown ramp  
area of a Cattle Dip  
Vat.**



A photograph showing a concrete drainage trench for a cattle dip vat. The trench is filled with dark, murky water and is heavily cluttered with debris, including sticks, twigs, and leaves. The concrete walls of the trench are made of large, rectangular blocks with a grid-like pattern of holes. The surrounding area is overgrown with dense vegetation, including green leafy plants and bare, tangled branches. The scene is outdoors, with natural light filtering through the trees.


**A view of the debris  
filled trench of a  
Cattle Dip Vat.**





**A fence used to  
guide the livestock  
into and out of the  
Cattle Dip Vat.**





**A fence used to  
guide the livestock  
into and out of the  
Cattle Dip Vat.**





**A fence used to guide the livestock into and out of the Cattle Dip Vat.**





**RZ05-1636 Part-B**

**Cattle Vat - 1**

**(Photo looking North West)**

**North Property Line  
6501 N 78th Street**

**A fenced off  
area containing  
a Cattle Dip Vat.**