SORT	CATEGORY	VIOLATION CODE	ASSOCIATED RULES	QUESTION	SIGNIF	REEVALUATION	RULE CAT
87	Aboveground	7001	62-762.101(5)	No reasonable access provided.	Minor	Inspection	62-762
88	Aboveground	7002	62-762.401(1)(b), 62-762.401(2), 62-762.401(3)(a), 62-762.401(3)(a), 62-762.401(3)(b), 62-762.401(3)(c)	Registration Form not submitted fora new system, change in service, closure, owner change, or discovery of unregistered facility.	Minor	Review	62-762
89	Aboveground	7003	62-762.401(4), 62-762.401(4)(a), 62-762.401(4)(a)1, 62-762.401(4)(a)2, 62-762.401(4)(b), 62-762.401(4)(c), 62-762.401(4)(d), 62-762.401(4)(e), 62-762.401(4)(f), 62-762.401(4)(g), 62-762.401(4)(h), 62-762.401(4)(i)	Registration fees not paid (not receiving fuel).	Minor	Review	62-762
90	Aboveground	7004	62-762.401(5)	Placard not displayed (or available upon request).	Minor	Review	62-762
91	Aboveground	7005	62-762.411(1)(b), 62-762.411(1)(c), 62-762.411(2), 62-762.411(2)(a), 62-762.411(2)(b), 62-762.411(2)(c)	Notification of installation, closure, or change in service status not received in required timeframes.	Minor	NCLI	62-762
92	Aboveground	7006	62-762.411(3)	Notification of internal inspection not received in an timely manner.	Minor	NCLI	62-762
93	Aboveground	7007	62-762.411(4)	Incident Notification Form (INF) not received in a timely manner.	Minor	NCLI	62-762
94	Aboveground	7008	62-762.411(5)	Discharge Notification Form (DRF) not received in a timely manner.	SNC-B	NCLI	62-762
95	Aboveground	7009	62-762.421(2), 62-762.421(3)(c)	No financial responsibility instrument or expired instrument for < 180 days.	SNC-B	Review	62-762
96	Aboveground	7010	62-762.421(2), 62-762.421(3)(c)	No financial responsibility instrument or expired instrument for > 180 days.	SNC-A	Review	62-762
97	Aboveground	7011	62-762.421(3), 62-762.421(3)(a), 62-762.421(3)(d), 62-762.421(3)(d)1, 62-762.421(3)(d)2, 62-762.421(3)(d)3, 62-762.421(3)(d)4, 62-762.421(8)	Appropriate paperwork for financial responsibility improperly completed or maintained.	Minor	Review	62-762
98	Aboveground	7012	62-762.431(2)	Incident investigation not initiated within 24-hours (or by next business day) to determine if discharge occurred.	SNC-B	NCLI	62-762
99	Aboveground	7013	62-762.431(4), 62-762.431(5)	Incident investigation leading to discharge not completed within 14 days, or No DRF or written confirmation received after 14 day investigation period.	Minor	Review	62-762
100	Aboveground	7014	62-762.431(6)	Removal of regulated substance from a release not initiated within three days and completed within 30 days of discovery.	SNC-B	NCLI	62-762
101	Aboveground	7015	62-762.431(8)	All incident records, including test results not kept until storage tank system closure.	Minor	NCLI	62-762

102	Aboveground	7016	62-762.441(2)	Discharge not reported with 24-hours, or by next business day.	SNC-B	NCLI	62-762
103	Aboveground	7017	62-762.441(3)	Analyticals not submitted with 24 -hours or next business day. OVA readings are not considered confirmation of discharge.	Minor	Review	62-762
104	Aboveground	7018	62-762.441(6), 62-762.441(6)(a), 62-762.441(6)(b), 62-762.441(6)(c), 62-762.441(6)(d), 62-762.441(6)(e), 62-762.441(6)(f), 62-762.441(6)(g)	Actions not taken immediately to contain, remove, and abate the discharge.	SNC-A	Review	62-762
105	Aboveground	7019	62-762.501(1)(b), 62-762.501(1)(b)1, 62-762.501(1)(b)1.a, 62-762.501(1)(b)1.b, 62-762.501(1)(b)1.c, 62-762.502(1)(b), 62-762.502(1)(b)1, 62-762.502(1)(b)1.a, 62-762.502(1)(b)1.b, 62-762.502(1)(b)1.c	Failure of secondary containment materials to meet standards.	SNC-B	Inspection	62-762
106	Aboveground	7020	62-762.501(1)(b)8, 62-762.501(1)(b)9, 62-762.501(1)(b)10, 62-762.501(1)(b)11, 62-762.502(1)(b)8, 62-762.502(1)(b)9, 62-762.502(1)(b)10	Integrity Testing of secondary containment systems and interstitial spaces not performed before being placed into service.	Minor	Inspection	62-762
107	Aboveground	7021	62-762.501(1)(b)2, 62-762.502(1)(b)2	Secondary containment using synthetic liners not in accordance with standards or not impervious.	Minor	Inspection	62-762
108	Aboveground	7022	62-762.501(1)(b)3, 62-762.501(1)(b)3.a, 62-762.501(1)(b)3.b, 62-762.501(1)(b)3.c, 62-762.501(1)(b)4, 62-762.502(1)(b)3, 62-762.502(1)(b)3.a, 62-762.502(1)(b)3.b, 62-762.502(1)(b)3.c, 62-762.502(1)(b)4	Secondary containment constructed of concrete not in accordance with standards or not impervious.	Minor	Inspection	62-762
109	Aboveground	7023	62-762.501(1)(b)5, 62-762.502(1)(b)5	VCI inhibitors are not contained by secondary containment system.	Minor	Review	62-762
110	Aboveground	7024	62-762.501(1)(b)6, 62-762.502(1)(b)6	Cathodically protected tanks and piping; secondary containment interferes with the operation of cathodic protection system.	Minor	Inspection	62-762
111	Aboveground	7025	62-762.501(1)(b)7, 62-762.502(1)(b)7	Secondary containment systems shall be designed and installed to direct any release to a monitoring point or points.	Minor	Inspection	62-762
112	Aboveground	7026	62-762.501(1)(c), 62-762.501(1)(c)1, 62-762.501(1)(c)2, 62-762.502(1)(c), 62-762.502(1)(c)1	Cathodic protection test station/method and operation does not meet standards. Or, secondary containment interferes with the cathodic protection system.	SNC-B	Inspection	62-762
113	Aboveground	7027	62-762.501(1)(c)3, 62-762.502(1)(c)3	Field installed cathodic protection not designed or installed by CP.	Minor	Inspection	62-762
114	Aboveground	7028	62-762.501(1)(d), 62-762.501(1)(d)1, 62-762.501(1)(d)2, 62-762.502(1)(d), 62-762.502(1)(d)1, 62-762.502(1)(d)2	Vapor Corrosion Inhibitors are not designed or installed by a Corrosion Professional and manufacturer for shop fabricated or field-erected tanks.	Minor	NCLI	62-762
115	Aboveground	7029	62-762.501(1)(e), 62-762.502(1)(e)	The primary and secondary wall linings are not compatible with the regulated substance.	SNC-B	Review	62-762

116	Aboveground	7030	62-762.501(1)(f), 62-762.502(1)(f)	Exterior coatings not protected from external corrosion, deterioration or degradation.	Minor	Inspection	62-762
117	Aboveground	7031	62-762.501(1)(i), 62-762.502(1)(i)	Any component(s) of storage tank system not installed according to manufacturer's instructions.	Minor	Inspection	62-762
118	Aboveground	7032	62-762.501(1)(g), 62-762.502(1)(g)	Any component(s) of storage tank system not installed according to reference standards.	SNC-B	Inspection	62-762
119	Aboveground	7033	62-762.501(1)(h), 62-762.501(1)(h)1, 62-762.501(1)(h)2, 62-762.501(1)(h)3, 62-762.501(1)(h)4	No signed or sealed survey drawing of the installed or relocated integral piping in contact with the soil.	Minor	Review	62-762
120	Aboveground	7034	62-762.502(1)(h), 62-762.501(2), 62-762.501(2)(a)	Storage Tanks are not installed according to applicable provisions.	SNC-B	Inspection	62-762
121	Aboveground	7035	62-762.501(2)(b), 62-762.501(2)(b)1, 62-762.501(2)(b)1.a, 62-762.501(2)(b)1.b, 62-762.501(2)(b)1.c, 62-762.501(2)(b)1.d, 62-762.501(2)(b)1.e, 62-762.501(2)(b)1.f, 62-762.501(2)(b)1.g, 62-762.501(2)(b)1.h, 62-762.501(2)(b)2, 62-762.502(2), 62-762.502(2)(a), 62-762.502(2)(b), 62-762.502(2)(b)1, 62-762.502(2)(b)1.a, 62-762.502(2)(b)1.b, 62-762.502(2)(b)2	Storage tanks not constructed according to manufacturer's instructions or reference standards or meet inspection schedule established.	SNC-B	Inspection	62-762
122	Aboveground	7036	62-762.501(2)(c), 62-762.501(2)(c)1, 62-762.502(2)(c), 62-762.502(2)(c)1, 62-762.502(2)(c)2	Cathodic protection installation does not meet requirements.	SNC-B	Inspection	62-762
123	Aboveground	7037	62-762.501(2)(c)3, 62-762.502(2)(c)3	Cathodic protection system not installed with test station or monitoring point.	Minor	Inspection	62-762
124	Aboveground	7038	62-762.501(2)(c)5, 62-762.502(2)(c)5	VCI not installed according to requirements.	Minor	Inspection	62-762
125	Aboveground	7039	62-762.501(2)(d), 62-762.501(2)(d)1, 62-762.501(2)(d)2, 62-762.501(2)(d)3, 62-762.501(2)(d)3.a, 62-762.501(2)(d)3.b, 62-762.501(2)(d)3.c, 62-762.501(2)(d)3.c.(I), 62-762.501(2)(d)3.c.(II), 62-762.501(2)(d)3.d, 62-762.502(2)(d), 62-762.502(2)(d)1, 62-762.502(2)(d)2, 62-762.502(2)(d)3, 62-762.502(2)(d)3.a, 62-762.502(2)(d)3.b, 62-762.502(2)(d)3.c, 62-762.502(2)(d)3.d, 62-762.502(2)(d)4, 62-762.502(2)(d)5, 62-762.502(2)(d)6, 62-762.502(2)(d)7	Secondary containment not installed per standards, including capacity requirements, drainage, and seal.	SNC-B	Inspection	62-762
126	Aboveground	7040	62-762.501(2)(e), 62-762.501(2)(e)1, 62-762.501(2)(e)2, 62-762.501(2)(e)2.a, 62-762.501(2)(e)2.b, 62-762.501(2)(e)2.c, 62-762.501(2)(e)2.d, 62-762.502(2)(e), 62-762.502(2)(e)1, 62-762.502(2)(e)2, 62-762.502(2)(e)3, 62-762.502(2)(e)3.a, 62-762.502(2)(e)3.b, 62-762.502(2)(e)3.c, 62-762.502(2)(e)3.d, 62-762.501(2)(e)5	Overfill protection not provided. Fuel transfer not monitored. Alarms not installed.	SNC-B	Inspection	62-762
127	Aboveground	7041	62-762.501(2)(e)3, 62-762.501(2)(e)3.a, 62-762.501(2)(e)3.b, 62-762.501(2)(e)4, 62-762.502(2)(e)4, 62-762.502(2)(e)4.a, 62-762.502(2)(e)4.b, 62-762.502(2)(e)5	Failure to designate, register, or annually test primary overfill protection device,	Minor	Review	62-762

128	Aboveground	7042	62-762.501(2)(f), 62-762.501(2)(f)1, 62-762.502(2)(f)	Storage tank system not installed with a spill containment system at each tank fill connection. Does not meet performance requirements.	SNC-B	Inspection	62-762
129	Aboveground	7043	62-762.501(2)(f)2	Fillbox covers not marked according to requirements.	Minor	Inspection	62-762
130	Aboveground	7044	62-762.501(2)(f)3	Spill containment systems not installed to allow for release detection.	SNC-B	Inspection	62-762
131	Aboveground	7045	62-762.501(2)(g), 62-762.501(2)(g)1	Dispensers not installed and maintained according to standards.	Minor	Inspection	62-762
132	Aboveground	7046	62-762.501(2)(g)2, 62-762.501(2)(g)3	Dispensers not installed with a dispenser sump, or allow for release detection.	SNC-B	Inspection	62-762
133	Aboveground	7047	62-762.501(2)(h), 62-762.501(2)(h)1, 62-762.502(2)(g), 62-762.502(2)(g)1	Piping sumps not meeting performance requirements or installed to allow for release detection.	SNC-B	Inspection	62-762
134	Aboveground	7048	62-762.501(2)(h)2, 62-762.502(2)(g)2	Piping sumps not installed to allow for release detection.	SNC-B	Inspection	62-762
135	Aboveground	7049	62-762.501(2)(i), 62-762.502(2)(h)	Hydrant sumps not installed or registered.	SNC-B	Inspection	62-762
136	Aboveground	7050	62-762.501(2)(j), 62-762.502(2)(i)	Aboveground storage tank system relocation requirements not met, not properly recertified, or does not meet current standards.	SNC-B	Inspection	62-762
137	Aboveground	7051	62-762.501(3), 62-762.501(3)(a), 62-762.501(3)(a)1	Pressurized piping or secondarily contained piping in contact with soil does not have appropriate testing, including breach of integrity, tightness or electronic leak detection.	SNC-B	Inspection	62-762
138	Aboveground	7052	62-762.501(3)(a)2	No interstitial integrity test on piping in contact with the soil before being placed in service.	SNC-B	Review	62-762
139	Aboveground	7053	62-762.501(3)(a)3	New integral piping not in contact with soil does not meet construction requirements.	SNC-B	Inspection	62-762
140	Aboveground	7054	62-762.501(3)(a)4	Integral piping not installed with a slope.	Minor	Inspection	62-762
141	Aboveground	7055	62-762.501(3)(a)5, 62-762.501(3)(a)6	Pressurized piping not installed with line leak detectors or does not meet requirements of paragraph 62-762.601(4)(b).	SNC-B	Inspection	62-762
142	Aboveground	7056	62-762.501(3)(b), 62-762.501(3)(b)1, 62-762.501(3)(b)2, 62-762.501(3)(b)3	Secondary containment not provided for small diameter integral piping.	SNC-B	Inspection	62-762
143	Aboveground	7057	62-762.501(3)(c), 62-762.501(3)(c)1, 62-762.501(3)(c)2, 62-762.501(3)(c)3, 62-762.501(3)(c)4, 62-762.501(3)(c)5	Piping in contact with soil not installed to standards.	SNC-B	Inspection	62-762

144	Aboveground	7058	62-762.501(3)(d)1, 62-762.501(3)(d)2, 62-762.501(3)(d)3	Valves do not meet standards of Section 7 of PEI/RP200-13 for piping systems with gravity head.	Minor	Inspection	62-762
145	Aboveground	7059	62-762.502(4), 62-762.502(4)(a), 62-762.502(4)(a)1, 62-762.502(4)(a)2	Bulk product piping not installed per manufacturer's instructions, or reference standards. Testing not completed prior to service.	SNC-B	Inspection	62-762
146	Aboveground	7060	62-762.502(4)(a)3	Integrity test not performed for underground bulk product piping for high viscosity products.	SNC-B	Review	62-762
147	Aboveground	7061	62-762.502(4)(b), 62-762.502(4)(b)1, 62-762.502(4)(b)2, 62-762.502(4)(b)3, 62-762.502(4)(b)4, 62-762.502(4)(b)5	Bulk product piping: Failure of secondary containment to meet standards for field erected tank systems.	SNC-B	Review	62-762
148	Aboveground	7062	62-762.502(4)(c), 62-762.502(4)(c)1, 62-762.502(4)(c)2, 62-762.502(4)(c)3	Bulk product piping not constructed according to reference standards or meet inspection schedule established.	SNC-B	Inspection	62-762
149	Aboveground	7063	62-762.601(1), 62-762.601(1)(a), 62-762.601(1)(b), 62-762.601(1)(c), 62-762.602(1), 62-762.602(1)(a), 62-762.602(1)(b), 62-762.602(1)(c)	Storage tank systems does not have appropriate testing, including breach of integrity, tightness or electronic leak detection.	SNC-A	Inspection	62-762
150	Aboveground	7064	62-762.601(1)(d), 62-762.601(1)(g), 62-762.602(1)(d), 62-762.602(1)(g)	Release detection not tested or visually inspected once a month or problems found during the visual inspections not recorded.	Minor	Review	62-762
151	Aboveground	7065	62-762.601(1)(e), 62-762.602(1)(e)	Storage tank system not visually inspected once a month.	SNC-B	Review	62-762
152	Aboveground	7066	62-762.601(1)(f), 62-762.602(1)(f), 62-762.601(1)(f)1, 62-762.602(1)(f)1	Electronic and mechanical release detection not installed, calibrated, operated and maintained per manufacturer's specifications.	SNC-B	Review	62-762
153	Aboveground	7067	62-762.601(1)(f)2, 62-762.602(1)(f)2	Electronic and mechanical release detection not registered.	Minor	Review	62-762
154	Aboveground	7068	62-762.601(1)(h), 62-762.602(1)(h)	Release detection not properly installed.	SNC-B	Review	62-762
155	Aboveground	7069	62-762.601(2), 62-762.601(2)(a), 62-762.601(2)(a)1, 62-762.601(2)(a)2, 62-762.601(2)(a)3, 62-762.601(2)(a)4, 62-762.601(2)(a)5, 62-762.601(2)(a)6, 62-762.601(2)(a)7, 62-762.601(2)(a)8, 62-762.602(2), 62-762.602(2)(a), 62-762.602(2)(a)1, 62-762.602(2)(a)2, 62-762.602(2)(a)3, 62-762.602(2)(a)4, 62-762.602(2)(a)5, 62-762.602(2)(a)6, 62-762.602(2)(a)7, 62-762.602(2)(a)8	Release detection does not meet standards.	SNC-B	Inspection	62-762
156	Aboveground	7070	62-762.601(3), 62-762.601(3)(a), 62-762.601(3)(b), 62-762.602(3), 62-762.602(3)(a), 62-762.602(3)(a)1, 62-762.602(3)(a)2, 62-762.602(3)(a)2.a, 62-762.602(3)(a)2.b, 62-762.602(3)(a)2.c	Storage tanks without secondary containment not visually inspected monthly.	SNC-B	Inspection	62-762

157	Aboveground	7071	62-762.601(4), 62-762.601(4)(a), 62-762.601(4)(b), 62-762.601(4)(b)1, 62-762.601(4)(b)2, 62-762.601(4)(b)3	Small diameter integral piping with secondary containment: Applicable release detection methods not used.	SNC-B	Review	62-762
158	Aboveground	7072	62-762.601(7), 62-762.602(7)	Annual operability testing of release detection systems not completed.	Minor	Review	62-762
159	Aboveground	7073	62-762.602(3)(b), 62-762.602(3)(b)1, 62-762.602(3)(b)2	No monthly visual inspection of aboveground or exempt bulk product pipe. Electronic sensing equipment not tested annually.	SNC-B	Review	62-762
160	Aboveground	7074	62-762.602(6), 62-762.602(6)(a), 62-762.602(6)(b), 62-762.602(6)(c), 62-762.602(6)(d)	Bulk product and hydrant piping without secondary containment does not have annual testing or visual inspections completed monthly.	SNC-B	Review	62-762
161	Aboveground	7075	62-762.701(1), 62-762.701(1)(a), 62-762.701(1)(a)1, 62-762.701(1)(a)2, 62-762.701(1)(a)3, 62-762.702(1), 62-762.702(1)(a), 62-762.702(1)(a)1, 62-762.702(1)(a)2, 62-762.702(1)(a)3	Not repaired component or piping which has not caused a discharge or release.	SNC-B	Inspection	62-762
162	Aboveground	7076	62-762.701(1), 62-762.701(1)(a), 62-762.701(1)(a)1, 62-762.701(1)(a)2, 62-762.701(1)(a)3, 62-762.702(1), 62-762.702(1)(a), 62-762.702(1)(a)1, 62-762.702(1)(a)2, 62-762.702(1)(a)3	Not repaired component or piping which has cause a discharge or release.	SNC-A	Inspection	62-762
163	Aboveground	7077	62-762.701(1)(b), 62-762.701(1)(b)1, 62-762.701(1)(b)2, 62-762.701(1)(b)3, 62-762.702(1)(b), 62-762.702(1)(b)1, 62-762.702(1)(b)2, 62-762.702(1)(b)3	Damaged system not taken out of service until repairs are made.	SNC-B	Inspection	62-762
164	Aboveground	7078	62-762.701(1)(c), 62-762.701(1)(c)1, 62-762.701(1)(c)2, 62-762.702(1)(c), 62-762.702(1)(c)1, 62-762.702(1)(c)2	System not repaired in accordance with manufacturer's instructions or applicable requirements.	Minor	Inspection	62-762
165	Aboveground	7079	62-762.701(1)(d)	Repairs not completed per applicable standards.	Minor	Inspection	62-762
166	Aboveground	7080	62-762.701(1)(e), 62-762.702(1)(d)	Repaired components not integrity tested before being placed back into operation.	Minor	Inspection	62-762
167	Aboveground	7081	62-762.701(1)(f), 62-762.701(1)(f)1, 62-762.701(1)(f)2, 62-762.702(1)(e), 62-762.702(1)(e)1, 62-762.702(1)(e)2	Piping that is damaged which has not caused a discharge is not replaced.	SNC-B	Inspection	62-762
168	Aboveground	7082	62-762.701(1)(f), 62-762.701(1)(f)1, 62-762.701(1)(f)2, 62-762.702(1)(e), 62-762.702(1)(e)1, 62-762.702(1)(e)2	Piping that is damaged which has caused a discharge is not replaced.	SNC-A	Inspection	62-762
169	Aboveground	7083	62-762.701(1)(g), 62-762.702(1)(f)	Storage tank system not taken out-of-service when repairs cannot be made within 90 days.	SNC-B	Inspection	62-762
170	Aboveground	7084	62-762.701(2), 62-762.701(2)(a), 62-762.702(2), 62-762.702(2)(a)	Cathodic and corrosion protection not operated and maintained to provide continuous protection, including inspection schedule. Not take out of service when requirement not met.	Minor	Inspection	62-762

171	Aboveground	7085	62-762.701(2)(b), 62-762.701(2)(b)1, 62-762.701(2)(b)2, 62-762.702(2)(b), 62-762.702(2)(b)1, 62-762.702(2)(b)2	Cathodic protection not inspected, tested and evaluated within six months of installation or repair, and at least yearly. Factory installed cathodic protection not tested, inspected or evaluated every 3 years.	Minor	Review	62-762
172	Aboveground	7086	62-762.701(2)(c), 62-762.702(2)(c)	Inpressed current and cathodic protection records not maintained.	Minor	Review	62-762
173	Aboveground	7087	62-762.701(2)(d), 62-762.701(2)(d)1, 62-762.701(2)(d)2, 62-762.702(2)(d), 62-762.702(2)(d)1, 62-762.702(2)(d)2	Cathodic protection systems cannot achieve or maintain protection, not repaired or closed in timeframes.	Minor	Inspection	62-762
174	Aboveground	7088	62-762.701(3), 62-762.701(3)(a), 62-762.701(3)(b), 62-762.701(3)(b)1, 62-762.701(3)(b)2, 62-762.701(3)(c), 62-762.701(3)(d), 62-762.701(3)(d)1, 62-762.701(3)(d)2, 62-762.702(3), 62-762.702(3)(a), 62-762.702(3)(b), 62-762.702(3)(b)1, 62-762.702(3)(b)2, 62-762.702(3)(c), 62-762.702(3)(d), 62-762.702(3)(d)1, 62-762.702(3)(d)2	Vapor corrosion inhibitor not operated and maintained to provide continuous protection, including inspection schedule. Not take out of service when requirement not met.	Minor	Review	62-762
175	Aboveground	7089	62-762.701(4), 62-762.701(4)(a), 62-762.701(4)(a)1, 62-762.701(4)(a)1.a, 62-762.701(4)(a)1.b, 62-762.701(4)(a)1.c, 62-762.701(4)(a)1.d, 62-762.701(4)(a)1.e, 62-762.701(4)(a)1.f, 62-762.701(4)(a)2, 62-762.702(4), 62-762.702(4)(a), 62-762.702(4)(a)1, 62-762.702(4)(a)1.a, 62-762.702(4)(a)1.b, 62-762.702(4)(a)1.c, 62-762.702(4)(a)1.d, 62-762.702(4)(a)2	Integrity testing of secondary containment systems and interstitial spaces not performed per schedule.	Minor	Review	62-762
176	Aboveground	7090	62-762.701(4)(b), 62-762.701(4)(b)1, 62-762.701(4)(b)2, 62-762.702(4)(b), 62-762.702(4)(b)1, 62-762.702(4)(b)2	Spill containment, dispenser liners and piping sumps not accessible; water and regulated substances not removed.	Minor	Review	62-762
177	Aboveground	7091	62-762.701(4)(c), 62-762.702(4)(c)	Exterior Coatings not maintained to prevent corrosion.	Minor	Inspection	62-762
178	Aboveground	7092	62-762.701(5), 62-762.701(5)(a), 62-762.701(5)(b), 62-762.701(5)(b)1, 62-762.701(5)(b)2, 62-762.701(5)(c), 62-762.701(5)(d), 62-762.702(5), 62-762.702(5)(a), 62-762.702(5)(b), 62-762.702(5)(b)1, 62-762.702(5)(b)2, 62-762.702(5)(c), 62-762.702(5)(d)	Stormwater not drawn off within one week.	Minor	Review	62-762
179	Aboveground	7093	62-762.702(6), 62-762.702(7)	Evaluation and testing not conducted in accordance with API standards or by a Florida licensed engineer.	Minor	Review	62-762
180	Aboveground	7094	62-762.711(1)	Permanent records not available within 5 working days notice.	Minor	Review	62-762
181	Aboveground	7095	62-762.711(2), 62-762.711(2)(a), 62-762.711(2)(b), 62-762.711(2)(c), 62-762.711(2)(d)	Records requiring 3 year documentation period not kept by facility.	Minor	Review	62-762
182	Aboveground	7096	62-762.711(3), 62-762.711(3)(a), 62-762.711(3)(b), 62-762.711(3)(c), 62-762.711(3)(d), 62-762.711(3)(e), 62-762.711(3)(f), 62-762.711(3)(g), 62-762.711(3)(h), 62-762.711(3)(i), 62-762.711(3)(j)	Records not kept until closure of system.	Minor	Review	62-762

183	Aboveground	7097	62-762.801(1), 62-762.801(1)(a), 62-762.801(1)(b), 62-762.801(1)(b)1, 62-762.801(1)(b)2, 62-762.801(1)(b)3, 62-762.801(1)(b)4, 62-762.801(1)(b)5, 62-762.801(1)(b)6, 62-762.802(2), 62-762.802(2)(a), 62-762.802(2)(b), 62-762.802(2)(b)1, 62-762.802(2)(b)2, 62-762.802(2)(b)3, 62-762.802(2)(b)4, 62-762.802(2)(b)5, 62-762.802(2)(b)6	Requirements not met for out of service systems including registering system out-of-service and securing out-of-service system.	Minor	Inspection	62-762
184	Aboveground	7098	62-762.801(1)(c)4, 62-762.801(1)(c)4.a, 62-762.801(1)(c)4.b, 62-762.802(2)(d)3, 62-762.802(2)(d)3.a, 62-762.802(2)(d)3.b	Testing shall be up-to-date and indicate proper operation before adding regulated substances to the storage tank system or returning system to service.	Minor	Review	62-762
185	Aboveground	7099	62-762.801(1)(d), 62-762.802(2)(e)	System with secondary containment out of service greater than 10 years.	SNC-B	Review	62-762
186	Aboveground	7100	62-762.801(1)(e), 62-762.802(2)(f)	System without secondary containment out of service greater than 5 years.	SNC-B	Review	62-762
187	Aboveground	7101	62-762.801(2), 62-762.801(2)(a), 62-762.801(2)(a)1, 62-762.801(2)(a)1.a, 62-762.801(2)(a)1.b, 62-762.801(2)(a)2, 62-762.801(2)(a)3, 62-762.801(2)(a)4, 62-762.802(3), 62-762.802(3)(a), 62-762.802(3)(a)1, 62-762.802(3)(a)1.a, 62-762.802(3)(a)1.b, 62-762.802(3)(a)2, 62-762.802(3)(a)3, 62-762.802(3)(a)4	Storage tank system not closed within 90 days in accordance with this subsection.	SNC-B	Review	62-762
188	Aboveground	7102	62-762.801(2)(b), 62-762.801(2)(b)1, 62-762.801(2)(b)2, 62-762.801(2)(b)3, 62-762.801(2)(b)4, 62-762.801(2)(b)5, 62-762.801(2)(b)6, 62-762.801(2)(b)7, 62-762.802(3)(b), 62-762.802(3)(b)1, 62-762.802(3)(b)2, 62-762.802(3)(b)3, 62-762.802(3)(b)4, 62-762.802(3)(b)5, 62-762.802(3)(b)6, 62-762.802(3)(b)7	Closure Integrity Report and Evaluation not completed and submitted in a timely fashion.	Minor	Inspection	62-762
189	Aboveground	7103	62-762.801(2)(b)8, 62-762.802(3)(b)8	Registration not updated for closure of storage tank system.	Minor	Review	62-762
190	Aboveground	7104	62-762.801(3), 62-762.801(3)(a), 62-762.801(3)(a)1, 62-762.801(3)(a)2, 62-762.801(3)(a)3, 62-762.801(3)(a)4, 62-762.801(3)(a)5, 62-762.801(3)(a)6, 62-762.801(3)(a)7, 62-762.802(4), 62-762.802(4)(a), 62-762.802(4)(a)1, 62-762.802(4)(a)2, 62-762.802(4)(a)3, 62-762.802(4)(a)4, 62-762.802(4)(a)5, 62-762.802(4)(a)6, 62-762.802(4)(a)7	Closure integrity Report not submitted.	Minor	Review	62-762
191	Aboveground	7105	62-762.801(3)(b), 62-762.802(4)(b)	Closure Report not submitted.	Minor	Review	62-762
192	Aboveground	7106	62-762.801(3)(c), 62-762.801(3)(c)1, 62-762.801(3)(c)2, 62-762.801(3)(c)3, 62-762.802(4)(c), 62-762.802(4)(c)1, 62-762.802(4)(c)2, 62-762.802(4)(c)3	Limited Closure Report not submitted.	Minor	Review	62-762
193	Aboveground	7107	62-762.802(1), 62-762.802(1)(a), 62-762.802(1)(b), 62-762.802(1)(c), 62-762.802(1)(d)	Requirements not met for field-erected tanks placed temporarily out of service.	Minor	Review	62-762
194	Aboveground	7108	62-762.802(2)(c)	Out of service bulk or field-erected storage tank systems not monitored annually.	Minor	Review	62-762
195	Aboveground	7109	62-762.802(2)(g), 62-762.851(1), 62-762.851(1)(a), 62-762.851(1)(b), 62-762.851(1)(b)1, 62-762.851(1)(b)2, 62-762.851(1)(b)3, 62-762.851(1)(b)4, 62-762.851(1)(b)5, 62-762.851(1)(b)6, 62-762.851(1)(b)7, 62-762.851(1)(c), 62-762.851(1)(c)1, 62-762.851(1)(c)2, 62-762.851(1)(d), 62-762.851(1)(e), 62-762.851(1)(f)	Facility not in compliance with Alternate Procedures.	Minor	Review	62-762

196	Aboveground	7110	62-762.851(2), 62-762.851(2)(a), 62-762.851(2)(b), 62-762.851(2)(c), 62-762.851(2)(d), 62-762.851(2)(e), 62-762.851(2)(f), 62-762.851(2)(f)1, 62-762.851(2)(f)2, 62-762.851(2)(f)3, 62-762.851(2)(f)4, 62-762.851(2)(f)5, 62-762.851(2)(f)6, 62-762.851(2)(g), 62-762.851(2)(h), 62-762.851(2)(i), 62-762.851(2)(i)1, 62-762.851(2)(i)2, 62-762.851(2)(i)3	Equipment not registered with DEP before installation or use.	Minor	Review	62-762
197	Aboveground	7111	62-762.891(3), 62-762.891(3)(a), 62-762.891(3)(b)	Mineral acid tank systems not registered.	Minor	Review	62-762
198	Aboveground	7112	62-762.891(3)(c)	No notification of change of registration information for Mineral Acid Tank.	Minor	Review	62-762
199	Aboveground	7113	62-762.891(3)(d), 62-762.891(3)(d)1, 62-762.891(3)(d)2, 62-762.891(4), 62-762.891(4)(a), 62-762.891(4)(b), 62-762.891(4)(b)1, 62-762.891(4)(b)1.a, 62-762.891(4)(b)1.b, 62-762.891(4)(b)1.c, 62-762.891(4)(b)2	Improper registration for Mineral Acid Tank.	Minor	Review	62-762
200	Aboveground	7114	62-762.891(4)(c)	Placard not displayed for Mineral Acid Tank.	Minor	Review	62-762
201	Aboveground	7115	62-762.891(5), 62-762.891(5)(a)	County not notified of CIP or secondary containment, by PE for Mineral Acid Tank.	Minor	Review	62-762
202	Aboveground	7116	62-762.891(5)(b)	Incident notification not submitted within 72-hours.	Minor	Review	62-762
203	Aboveground	7117	62-762.891(5)(c), 62-762.891(5)(c)1, 62-762.891(5)(c)2, 62-762.891(5)(c)3	Mineral Acid Tank: Discharge not reported with 24-hours, or by next business day.	SNC-B	Review	62-762
204	Aboveground	7118	62-762.891(6), 62-762.891(6)(a), 62-762.891(6)(a)1, 62-762.891(6)(a)2	No secondary containment or CIP for mineral acid tanks.	SNC-B	Review	62-762
205	Aboveground	7119	62-762.891(6)(b), 62-762.891(6)(b)1, 62-762.891(6)(b)2, 62-762.891(6)(b)3	Secondary containment for Mineral Acid Tank not certified by PE.	Minor	Review	62-762
206	Aboveground	7120	62-762.891(6)(c), 62-762.891(6)(c)1	CIP not certified by PE.	Minor	Review	62-762
207	Aboveground	7121	62-762.891(6)(c)2, 62-762.891(6)(c)2.a, 62-762.891(6)(c)2.b, 62-762.891(6)(c)2.c, 62-762.891(6)(c)2.d, 62-762.891(6)(c)2.e, 62-762.891(6)(c)2.f, 62-762.891(6)(c)2.g, 62-762.891(6)(c)2.h, 62-762.891(6)(c)2.i	CIP for Mineral Acid Tank does not meet requirements or certified by PE.	Minor	Review	62-762
208	Aboveground	7122	62-762.891(7), 62-762.891(7)(a), 62-762.891(7)(b), 62-762.891(7)(c)	Records not kept for Mineral Acid Tank(s).	Minor	Review	62-762
209	Aboveground	7123	62-762.891(8), 62-762.891(8)(a), 62-762.891(8)(a)1, 62-762.891(8)(a)2, 62-762.891(8)(a)3, 62-762.891(8)(b)	Appropriate actions not taken in the event of a discharge.	SNC-A	Inspection	62-762