SORT	CATEGORY	VIOLATION CODE	ASSOCIATED RULES	QUESTION	SIGNIF	REEVALUATION	RULE CAT
1	Underground	6001	62-761.100(3)	No reasonable access provided.	Minor	Inspection	62-761
2	Underground	6002	62-761.350(1), 62-761.350(1)(c), 62-761.350(1)(d), 62-761.350(3)(b)2, 62-761.350(5)(a), 62-761.350(5)(b), 62-761.350(5)(c), 62-761.350(7)	Operator Training records not available.	Minor	Review	62-761
3	Underground	6003	62-761.400(1)(b), 62-761.400(2), 62-761.400(2)(a), 62-761.400(3), 62-761.400(3)(a), 62-761.400(3)(b), 62-761.400(3)(c)	Registration Form not submitted for a new system, change in service, closure, owner change, or discovery of unregistered facility.	Minor	Review	62-761
4	Underground	6004	62-761.400(1)(c), 62-761.400(2)(b)	For Installation or Closure, Certified Contractors Form not submitted.	Minor	Review	62-761
5	Underground	6005	62-761.400(4), 62-761.400(4)(a), 62-761.400(4)(b), 62-761.400(4)(c), 62-761.400(4)(d), 62-761.400(4)(e), 62-761.400(4)(f)	Registration fees not paid (not receiving fuel).	Minor	Review	62-761
6	Underground	6006	62-761.400(5)	Placard not displayed (or available upon request).	Minor	Review	62-761
7	Underground	6007	62-761.400(7), 62-761.400(7)(a), 62-761.400(7)(b)	Owner, operator, or supplier deposited motor fuel into storage tank without current valid registration placard.	SNC-A	NCLI	62-761
8	Underground	6008	62-761.405(1), 62-761.405(1)(a), 62-761.405(1)(b), 62-761.405(1)(c), 62-761.405(2), 62-761.405(2)(a), 62-761.405(2)(b), 62-761.405(2)(c), 62-	For installation, closure, or change in service status, notification not received in a timely manner.	Minor	NCLI	62-761
9	Underground	6009	62-761.405(3)	Incident Notification Form (INF) not received in a timely manner.	Minor	NCLI	62-761
10	Underground	6010	62-761.405(4)	Discharge Notification Form (DRF) not received in a timely manner.	SNC-B	NCLI	62-761
11	Underground	6011	62-761.420(2)	No financial responsibility instrument or expired instrument for < 180 days.	SNC-B	Review	62-761

12	Underground	6012	62-761.420(2)	No financial responsibility instrument or expired instrument for > 180 days.	SNC-A	Review	62-761
13	Underground	6013	62-761.420(3), 62-761.420(4), 62-761.420(8)	Appropriate paperwork for financial responsibility improperly completed or maintained.	Minor	Review	62-761
14	Underground	6014	62-761.430(2)	Incident investigation not initiated within 24-hours (or by next business day) to determine if discharge occurred.	SNC-B	NCLI	62-761
15	Underground	6015	62-761.430(4), 62-761.430(5)	Incident investigation not completed within 14 days, and/or no DRF or written confirmation received at the end of the 14-day investigation period.	Minor	Review	62-761
16	Underground	6016	62-761.430(6)	Removal of regulated substance from a release into secondary containment not initiated within three days and completed within 30 days of discovery.	SNC-B	Inspection	62-761
17	Underground	6017	62-761.430(8)	All incident records, including test results not kept until storage tank system closure.	Minor	NCLI	62-761
18	Underground	6018	62-761.440(2)	Discharge not reported within 24-hours, or by next business day.	SNC-B	NCLI	62-761
19	Underground	6019	62-761.440(3)	Analyticals not submitted with 24 -hours or next business day. OVA readings are not considered confirmation of discharge.	Minor	Review	62-761
20	Underground	6020	62-761.440(6), 62-761.440(6)(a), 62-761.440(6)(b), 62-761.440(6)(c), 62-761.440(6)(d), 62-761.440(6)(e), 62-761.440(6)(f), 62-761.440(6)(g)	Actions not taken immediately to contain, remove, and abate the discharge.	SNC-A	Inspection	62-761
21	Underground	6021	62-761.500(1), 62-761.500(1)(b)1, 62-761.500(1)(b)1.a, 62-761.500(1)(b)1.b, 62-761.500(1)(b)1.c	Failure of secondary containment to meet standards including: impervious spill containment, liners, allowing for release detection, allow for monitoring point, and	SNC-B	Inspection	62-761
22	Underground	6022	62-761.500(1)(b)2, 62-761.500(1)(c)1	Cathodic protection test station/method and operation does not meet standards. Or, secondary containment interferes with the cathodic protection system.	SNC-B	Inspection	62-761
23	Underground	6023	62-761.500(1)(b)3, 62-761.500(3)(e)	Secondary containment or integral piping not installed to allow for monitoring point.	Minor	Inspection	62-761

24	Underground	6024	62-761.500(1)(b)4, 62-761.500(1)(b)5, 62-761.500(1)(b)6, 62-761.500(1)(b)7	Integrity test not performed on storage tank, integral piping, single-walled spill containment system, double-walled spill containment system, or doubled-walled	Minor	Review	62-761
25	Underground	6025	62-761.500(1)(c)3, 62-761.500(3)(i)	Field installed cathodic protection or corrosion protection system with vapor corrosion inhibitors not installed by or under direction of a Corrosion Professional.	Minor	Inspection	62-761
26	Underground	6026	62-761.500(1)(c)4	Corrosion protection not provided for former single-walled storage tank upgraded to secondary containment by installation of field-fabricated primary storage tank.	SNC-B	Inspection	62-761
27	Underground	6027	62-761.500(1)(c)5	Supplemental anodes are not installed in accordance with guidelines.	Minor	Inspection	62-761
28	Underground	6028	62-761.500(1)(d)	The primary and secondary wall linings are not compatible with the regulated substance.	SNC-B	Review	62-761
29	Underground	6029	62-761.500(1)(e)	Any component(s) of the storage tank system not installed according to manufacturer's instructions.	Minor	Inspection	62-761
30	Underground	6030	62-761.500(1)(f), 62-761.500(1)(f)1, 62-761.500(1)(f)2, 62-761.500(1)(f)3, 62-761.500(1)(f)4, 62-761.500(1)(f)5	Any component(s) of storage tank system not installed according to reference standards.	SNC-B	Inspection	62-761
31	Underground	6031	62-761.500(1)(g), 62-761.500(1)(g)1, 62-761.500(1)(g)2	Any component(s) of storage tank system not installed according to manufacturer's specification.	SNC-B	Inspection	62-761
32	Underground	6032	62-761.500(1)(h)	Work not performed by a Certified Contractor.	SNC-B	Review	62-761
33	Underground	6033	62-761.500(1)(i)	Survey of ground contact and underground components not conducted or maintained.	Minor	Review	62-761
34	Underground	6034	62-761.500(2), 62-761.500(2)(a), 62-761.500(2)(b), 62-761.500(2)(c), 62-761.500(2)(c)1, 62-761.500(2)(c)2, 62-761.500(2)(c)3, 62-761.500(2)(c)4, 62-	Storage tanks not installed according to manufacturer's instructions or reference standards.	SNC-B	Inspection	62-761
35	Underground	6035	62-761.500(2)(h), 62-761.500(2)(h)1, 62-761.500(2)(h)2, 62-761.500(2)(h)3	Underground tank relocation requirements not met, or reused tanks not properly recertified.	SNC-B	Inspection	62-761

36	Underground	6036	62-761.500(3), 62-761.500(3)(a), 62-761.500(3)(b), 62-761.500(3)(c)	Integral piping not installed to standards or installed without secondary containment.	SNC-B	Inspection	62-761
37	Underground	6037	62-761.500(3)(d), 62-761.500(3)(d)1, 62-761.500(3)(d)2, 62-761.500(3)(d)3, 62-761.500(3)(d)4, 62-761.500(3)(d)5	Piping in contact with soil not installed to standards.	SNC-B	Inspection	62-761
38	Underground	6038	62-761.500(3)(f)	Shear valve not installed properly.	SNC-B	Inspection	62-761
39	Underground	6039	62-761.500(3)(g)	Small diameter piping with gravity head not properly installed or meeting standards.	Minor	Inspection	62-761
40	Underground	6040	62-761.500(3)(h)	Pressurized integral piping connected to dispensers not installed with leak detection method.	SNC-B	Inspection	62-761
41	Underground	6041	62-761.500(3)(j)	Piping not meeting the Bulk Product Piping Requirements	Minor	Review	62-761
42	Underground	6042	62-761.500(4)(a)	Storage tank system not installed with a spill containment system at each tank fill connection. Does not meet performance requirements.	SNC-B	Inspection	62-761
43	Underground	6043	62-761.500(4)(b)	Fillbox covers not marked according to requirements.	Minor	Inspection	62-761
44	Underground	6044	62-761.500(4)(c)	Single-walled spill containment systems not installed to allow for release detection.	Minor	Inspection	62-761
45	Underground	6045	62-761.500(4)(d)	Double-walled spill containment system does not allow for interstitial monitoring.	Minor	Inspection	62-761
46	Underground	6046	62-761.500(5)(a)	Dispensers not installed and maintained according to standards.	Minor	Inspection	62-761
47	Underground	6047	62-761.500(5)(b)	Dispensers not installed with a dispenser sump.	SNC-B	Inspection	62-761

48	Underground	6048	62-761.500(5)(c)	Dispenser sumps not installed to allow for release detection.	SNC-B	Inspection	62-761
49	Underground	6049	62-761.500(6)(a)	Piping sumps not meeting performance requirements.	SNC-B	Inspection	62-761
50	Underground	6050	62-761.500(6)(b)	Piping sumps not installed to allow for release detection.	SNC-B	Inspection	62-761
51	Underground	6051	62-761.500(7)(a)	Overfill prevention not provided or properly functioning.	SNC-B	Inspection	62-761
52	Underground	6052	62-761.500(7)(b), 62-761.500(7)(b)1, 62-761.500(7)(b)2, 62-761.500(7)(b)3	Overfill that shuts off/restricts flow or triggers alarm not provided.	SNC-B	Inspection	62-761
53	Underground	6053	62-761.500(7)(c), 62-761.500(7)(c)1, 62-761.500(7)(c)2, 62-761.500(7)(d)	Primary overfill protection not provided, registered, or tested as required.	Minor	Review	62-761
54	Underground	6054	62-761.500(7)(e)	Tanks filled without mated tight fill adaptor connection filled beyond 95 percent capacity.	SNC-B	Review	62-761
55	Underground	6055	62-761.600(1), 62-761.600(1)(a), 62-761.600(1)(b), 62-761.600(1)(c), 62-761.600(1)(i)	Cannot detect a release from any portion of the system. (Including Emergency power generator storage tank systems installed prior to rule do not meet release detection	SNC-A	Inspection	62-761
56	Underground	6056	62-761.600(1)(d), 62-761.600(1)(e), 62-761.600(1)(g)	Release detection not tested or visually inspected once a month or problems found during the visual inspections not recorded.	SNC-B	Review	62-761

57	Underground	6057	62-761.600(1)(f), 62-761.600(1)(f)1	Release detection not installed, operated, and maintained per manufacturer's instructions and standards.	SNC-B	Inspection	62-761
58	Underground	6058	62-761.600(1)(f)2	Electronic and mechanical release detection devices not registered with the department.	Minor	Review	62-761
59	Underground	6059	62-761.600(1)(h)	Release detection shall be constructed and installed so that groundwater, rainfall, or soil moisture will not render the release detection method used inoperable.	SNC-B	Inspection	62-761
60	Underground	6060	62-761.600(2), 62-761.600(2)(a), 62-761.600(2)(a)1, 62-761.600(2)(a)2, 62-761.600(2)(a)3, 62-761.600(2)(a)4, 62-761.600(2)(a)5, 62-761.600(2)(a)6, 62-	Release detection methods do not meet monitoring requirements.	SNC-B	Inspection	62-761
61	Underground	6061	62-761.600(3), 62-761.600(3)(a), 62-761.600(3)(b), 62-761.600(3)(b)1, 62-761.600(3)(b)2, 62-761.600(3)(b)3	Release detection devices for integral piping do not meet general standards.	SNC-B	Review	62-761
62	Underground	6062	62-761.600(4)	Release detection devices not tested annually.	Minor	Review	62-761
63	Underground	6063	62-761.700(1), 62-761.700(1)(a), 62-761.700(1)(a)1, 62-761.700(1)(a)2	Not repaired or isolated component or piping which has not caused a discharge or release.	SNC-B	Inspection	62-761
64	Underground	6064	62-761.700(1), 62-761.700(1)(a), 62-761.700(1)(a)1, 62-761.700(1)(a)2	Not repaired or isolated component or piping which has cause a discharge or release.	SNC-A	Inspection	62-761
65	Underground	6065	62-761.700(1)(b), 62-761.700(1)(b)1, 62-761.700(1)(b)2, 62-761.700(1)(b)3	Damaged system not taken out of service or out of operation until repair is made.	SNC-B	Inspection	62-761
66	Underground	6066	62-761.700(1)(c), 62-761.700(1)(c)1, 62-761.700(1)(c)2	Not repaired per applicable standards.	Minor	Inspection	62-761
67	Underground	6067	62-761.700(1)(d)	Integrity test not completed before being placed into operation or service.	Minor	Inspection	62-761
68	Underground	6068	62-761.700(1)(e)	Storage tank system not closed within 90 days in accordance with subsection.	SNC-B	Inspection	62-761

69	Underground	6069	62-761.700(2), 62-761.700(2)(a), 62-761.700(2)(b), 62-761.700(2)(b)1, 62-761.700(2)(b)2	Cathodic protection not operated and maintained to provide continuous protection. System not inspected 6 months after	Minor	Review	62-761
70	Underground	6070	62-761.700(2)(c)	Records for operation of impressed current systems not complete.	Minor	Review	62-761
71	Underground	6071	62-761.700(2)(d), 62-761.700(2)(d)1, 62-761.700(2)(d)2	Cathodic protection systems that do not meet requirements not repaired in 90 days or storage tank system closed.	Minor	Inspection	62-761
72	Underground	6072	62-761.700(3), 62-761.700(3)(a), 62-761.700(3)(a)1, 62-761.700(3)(a)1.a, 62-761.700(3)(a)1.b, 62-761.700(3)(a)1.c, 62-761.700(3)(a)1.d, 62-761.700(3)(a)1.e, 62-	Integrity testing of secondary containment systems and interstitial spaces not performed per schedule.	Minor	Inspection	62-761
73	Underground	6073	62-761.700(3)(b), 62-761.700(3)(b)1, 62-761.700(3)(b)2	Spill containment, dispenser liners, and piping sumps not accessible. Water or regulated substances not removed.	Minor	Review	62-761
74	Underground	6074	62-761.710(1), 62-761.710(2), 62-761.710(2)(a), 62-761.710(2)(b), 62-761.710(2)(c), 62-761.710(2)(d), 62-761.710(3), 62-761.710(3)(a), 62-	Improper maintenance of records. Records requring to be maintained for 3 years or for the life of the system not kept by facility. Records not provided within 5 business days.	Minor	Review	62-761
75	Underground	6075	62-761.710(4)	Records of current training certificates for designated Class A, B, and C operators shall be maintained for as long as the operators are designated for that facility not kept.	Minor	Review	62-761
76	Underground	6076	62-761.800(1), 62-761.800(1)(b), 62-761.800(1)(b)1, 62-761.800(1)(b)2, 62-761.800(1)(b)3, 62-761.800(1)(b)4, 62-761.800(1)(b)5, 62-761.800(1)(b)6	Requirements not met for out-of-service systems.	Minor	Inspection	62-761

77	Underground	6077	62-761.800(1)(c), 62-761.800(1)(d)4	Out of service storage tank systems not tested annually for operability or interstice and liquid level not monitored annually.	Minor	Inspection	62-761
78	Underground	6078	62-761.800(1)(e)	Storage tanks systems with secondary containment designated out of service greater than 10 years.	SNC-B	Review	62-761
79	Underground	6079	62-761.800(2), 62-761.800(2)(a), 62-761.800(2)(a)1, 62-761.800(2)(a)2, 62-761.800(2)(a)3	USTs not closed with 90 days of discovery, or not meeting requirements, unable to be repaired or no FR.	SNC-B	Inspection	62-761
80	Underground	6080	62-761.800(2)(b), 62-761.800(2)(b)1, 62-761.800(2)(b)2, 62-761.800(2)(b)3, 62-761.800(2)(b)4, 62-761.800(2)(b)5, 62-761.800(2)(b)6	Storage tank system closure requirements not met that did not result in a discharge.	SNC-B	Inspection	62-761
81	Underground	6081	62-761.800(2)(b), 62-761.800(2)(b)1, 62-761.800(2)(b)2, 62-761.800(2)(b)3, 62-761.800(2)(b)4, 62-761.800(2)(b)5, 62-761.800(2)(b)6	Storage tank system closure requirements not met that resulted in a discharge.	SNC-A	Inspection	62-761
82	Underground	6082	62-761.800(3), 62-761.800(3)(a), 62-761.800(3)(a)1, 62-761.800(3)(a)2, 62-761.800(3)(a)3, 62-761.800(3)(a)4, 62-761.800(3)(a)5, 62-761.800(3)(a)6	Closure Integrity Report and Evaluation not completed and submitted in a timely fashion.	Minor	Review	62-761
83	Underground	6083	62-761.800(3)(b)	Closure assessment, sampling not performed and submitted within 60 days.	SNC-B	Review	62-761
84	Underground	6084	62-761.800(3)(c), 62-761.800(3)(c)1, 62-761.800(3)(c)2, 62-761.800(3)(c)3	Closure assessment not performed or properly completed.	SNC-B	Review	62-761
85	Underground	6085	62-761.850(1), 62-761.850(1)(a), 62-761.850(1)(b), 62-761.850(1)(b)1, 62-761.850(1)(b)2, 62-761.850(1)(b)3, 62-761.850(1)(b)4, 62-761.850(1)(b)5, 62-	Facility not in compliance with Alternate Procedure.	Minor	Review	62-761
86	Underground	6086	62-761.850(2), 62-761.850(2)(a), 62-761.850(2)(b), 62-761.850(2)(c), 62-761.850(2)(e), 62-761.850(2)(f), 62-761.850(2)(f)1, 62-761.850(2)(f)2, 62-	Equipment not registered with DEP before installation or use.	Minor	Review	62-761