

DEP's Daily Update on Mosaic – New Wales Sinkhole

Ongoing Oversight for September 2017

- **Sept. 28, 2017:** DEP and Mosaic took joint samples of Mosaic monitoring wells. Results from these samples are forthcoming.
- **Sept. 26, 2017:** DEP and Mosaic took joint samples of Mosaic monitoring wells. Results from these samples are forthcoming.
- **Sept. 25, 2017:** DEP and Mosaic took joint samples of Mosaic monitoring wells. Results from these samples are forthcoming.
- **Sept. 20, 2017:** DEP and Mosaic took joint samples of Mosaic monitoring wells. Results from these samples are forthcoming.
- **Sept. 19, 2017:** DEP and Mosaic took joint samples of Mosaic monitoring wells. Results from these samples are forthcoming.
- **Sept. 18, 2017:** DEP and Mosaic took joint samples of Mosaic monitoring wells. Results from these samples are forthcoming.
- **Sept. 15, 2017:** DEP staff performed post-storm inspection of the New Wales site and gypsum stack system. DEP confirmed Mosaic had resumed remedial activities at the site and no storm related impacts were noted. DEP is conducting inspections of all Mosaic active gypsum stack systems as part of post-storm response efforts to ensure no there are no post-storm environmental concerns.
- **Sept. 6, 2017:** DEP obtained status update from Mosaic on pre-storm site preparation activities, including status of generators that are onsite and fuel supplies to ensure recovery wells remain operational should there be a loss of power due to Hurricane Irma.
- **Sept. 6, 2017:** DEP and ECT took joint samples from private drinking water wells. Results from these samples are forthcoming.
- **Sept. 6, 2017:** DEP and Mosaic took joint samples of Mosaic monitoring wells. Results from these samples are forthcoming.
- **Sept. 5, 2017:** DEP and ECT took joint samples from private drinking water wells. Results from these samples are forthcoming.
- **Sept. 5, 2017:** DEP and Mosaic took joint samples of Mosaic monitoring wells. Results from these samples are forthcoming.