Geosyntec consultants

19321 U.S. Highway 19 North, Building C, Suite 200
Clearwater, Florida 33764
PH 813.792.4820
www.geosyntec.com

1 June 2021

Mr. Robert Cilek
Florida Department of Environmental Protection
2600 Blair Stone Road
Tallahassee, Florida 32399-2400

**Subject:** **Trip Report – Monitoring Well Installation and Investigation-Derived Waste Disposal – May 2021**
**Former Florida State Fire College**
**1501 W Silver Springs Blvd, Ocala, Marion County, Florida**
**ERIC_5641**
**FDEP Contract HW550, Task Assignment SOL-0A118, Subtasks 4 and 6**

Dear Mr. Cilek,

Geosyntec Consultants, Inc. (Geosyntec) has prepared this Trip Report summarizing the installation of monitoring wells using the rotosonic drilling method at the Former Florida State Fire College (FFSFC) located in Ocala, Florida. The objective of this investigation was to assess the extent of groundwater that was previously documented to be affected with per- and polyfluoroalkyl substances. This Trip Report also summarizes the transportation and disposal of investigation-derived waste (IDW). Geosyntec completed activities under Task Assignment SOL-0A118.

Between 17 May and 27 May 2021, Geosyntec completed the following activities at FFSFC:

- Observed a private utility locate to identify any potential subsurface utilities or obstructions;
- Established the staging area at FFSFC for equipment, materials, and IDW;
- Observed the construction of the decontamination pit that was used throughout well installation activities;
- Observed the installation of 8 monitoring wells (DEPMW-1 through DEPMW-8) for the investigation of PFAS-impacted groundwater associated with FFSFC (1 well screened from 20 to 40 feet below land surface [ft BLS], 3 wells screened from 25 to 45 ft BLS, and 4 wells screened from 100 to 120 ft BLS);
- Collected core samples for lithologic description at 4 well cluster locations;
- Collected two equipment blanks (EQB-40 and EQB-41) and one field reagent blank (FRB-7);

Geosyntec consultants

- Staged forty-eight (48) 55-gallon drums containing soil and liquid investigation derived waste in the designated area; and
- Observed the removal of the forty-eight (48) 55-gallon drums of IDW by the waste hauler.

The monitoring well locations with updated Global Positioning System coordinates are depicted on **Figure 1**. Field notes are included in **Attachment A**, and a photographic log documenting representative field activities is included in **Attachment B**. The non-hazardous waste manifest is included in **Attachment C**. A final waste manifest signed by the designated facility owner will be forwarded upon receipt.

If you have any questions or comments, or require additional information, please contact Eric Sager at 727-330-9952.

Sincerely,

Boone Abbott, G.I.T. (AL)
Senior Staff Geologist

Eric Sager, P.G. (FL)
Senrior Principal Geologist

Copy: David Meyers, Florida Department of Environmental Protection
Todd Kafka, Geosyntec

Attachments: Figure
Attachment A – Field Forms
Attachment B – Photographic Log

# FIGURE




**Figure 1**
**Monitoring Well Location Map**
**Former Florida State Fire College**
**1501 West Silver Springs Boulevard**
**Ocala, Marion County, Florida**

**Notes:**
1. Site and parcel boundaries obtained from Florida Department of Revenue Property Tax Oversight website (https://floridarevenue.com/property/Pages/DataPortal_RequestAssessmentRollGISData.aspx ), Marion County 2020.
2. 2019 World Imagery Source: Esri, Maxar, GeoEye, Earthstar Geographics, CNES/Airbus DS, USDA, USGS, AeroGRID, IGN, and the GIS User Community.

**Date: May 28, 2021**

N

160 Feet

FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

Path: (Titusville-01\DATA) T:\0GIS\FR7522_FormerFSFC\MXDs\202104\New_Locs_site_vicinity.mxd 28 May 2021. Last Edited by: mhensley

**ATTACHMENT A**

Field Notes

## Attachment A. Daily Sampling Checklist

Date: 5-17-21

Site Name: Former FSFC

Weather (*temperature/precipitation*): Sunny 85

**Please check all boxes that apply and describe any exceptions in the notes section below along with QA/QC methods used to assess potential sample cross-contamination as a result.**

Field Clothing and PPE:

- [x] No water- or stain-resistant boots or clothing (e.g., GORE-TEX®)
- [x] Field boots (or overboots) are made of polyurethane, PVC, rubber, or untreated leather
- [x] Rain gear are made of polyurethane, PVC, vinyl, wax-coated or rubber
- [x] Clothing has not been recently laundered with a fabric softener
- [x] No coated HDPE suits (e.g., coated Tyvek® suits)
- [x] Field crew has not used cosmetics, moisturizers, or other related products today
- [x] Field crew has not used sunscreen or insect repellants today, other than products approved as PFAS-free

not surface water sampling or sediment sampling

Field Equipment:

- [x] Sample containers and equipment in direct contact with the sample are made of HDPE, polypropylene, silicone, acetate or stainless steel, not LDPE or glass
- [x] Sample caps are made of HDPE or polypropylene and are not lined with Teflon™
- [x] No materials containing Teflon™, Viton™, or fluoropolymers
- [x] No materials containing LDPE in direct contact with the sample (e.g., LDPE tubing, Ziploc® bags)
- [x] No plastic clipboards, binders, or spiral hard cover notebooks
- [x] No waterproof field books
- [x] No waterproof or felt pens or markers (e.g., certain Sharpie® products)
- [x] No chemical (blue) ice, unless it is contained in a sealed bag
- [x] No aluminum foil
- [x] No sticky notes (e.g., certain Post-It® products)

Decontamination:

- [x] Reusable field equipment (e.g., dip sampler) decontaminated prior to reuse
- [x] "PFAS-free" water is on-site for decontamination of field equipment
- [x] Alconox®, Liquinox® or Luminox® used as decontamination detergent

Food and Drink:

- ☑ No food or drink on-site, except within staging area
- ☑ Food in staging area is contained in HDPE or stainless steel container

Notes:

water proof boots worn, SOPs modified to no water proof boots / over boots during sediment + surface water sampling

Field Team Leader Name (Print): Boone Abbott

Field Team Leader Signature: [signature]

Date/Time: 5-17-21 1134

## Attachment A. Daily Sampling Checklist

Date: 5-18-21

Site Name: Former FSFC

Weather (*temperature/precipitation*): Sunny 85°

**Please check all boxes that apply and describe any exceptions in the notes section below along with QA/QC methods used to assess potential sample cross-contamination as a result.**

Field Clothing and PPE:

- ☑ No water- or stain-resistant boots or clothing (e.g., GORE-TEX®)
- ☐ Field boots (or overboots) are made of polyurethane, PVC, rubber, or untreated leather (not surface water or sediment sampling)
- ☑ Rain gear are made of polyurethane, PVC, vinyl, wax-coated or rubber
- ☑ Clothing has not been recently laundered with a fabric softener
- ☑ No coated HDPE suits (e.g., coated Tyvek® suits)
- ☑ Field crew has not used cosmetics, moisturizers, or other related products today
- ☑ Field crew has not used sunscreen or insect repellants today, other than products approved as PFAS-free

Field Equipment:

- ☑ Sample containers and equipment in direct contact with the sample are made of HDPE, polypropylene, silicone, acetate or stainless steel, not LDPE or glass
- ☑ Sample caps are made of HDPE or polypropylene and are not lined with Teflon™
- ☑ No materials containing Teflon™, Viton™, or fluoropolymers
- ☑ No materials containing LDPE in direct contact with the sample (e.g., LDPE tubing, Ziploc® bags)
- ☑ No plastic clipboards, binders, or spiral hard cover notebooks
- ☑ No waterproof field books
- ☑ No waterproof or felt pens or markers (e.g., certain Sharpie® products)
- ☑ No chemical (blue) ice, unless it is contained in a sealed bag
- ☑ No aluminum foil
- ☑ No sticky notes (e.g., certain Post-It® products)

Decontamination:

- ☑ Reusable field equipment (e.g., dip sampler) decontaminated prior to reuse
- ☑ "PFAS-free" water is on-site for decontamination of field equipment
- ☑ Alconox®, Liquinox® or Luminox® used as decontamination detergent

Food and Drink:

- ☑ No food or drink on-site, except within staging area
- ☑ Food in staging area is contained in HDPE or stainless steel container

Notes:

water proof boots worn without overboots

SOPs modified to no water proof boots or overboots worn only during sediment + surface water sampling

Field Team Leader Name (Print): Boone Abbott

Field Team Leader Signature: [signature]

Date/Time: 5-18-21 0710

## Attachment A. Daily Sampling Checklist

Date: 5-19-21

Site Name: Former FSFC

Weather (*temperature/precipitation*): Sunny 84

**Please check all boxes that apply and describe any exceptions in the notes section below along with QA/QC methods used to assess potential sample cross-contamination as a result.**

Field Clothing and PPE:

not sediment or surface water sampling

- ☐ No water- or stain-resistant boots or clothing (e.g., GORE-TEX®)
- ☐ Field boots (or overboots) are made of polyurethane, PVC, rubber, or untreated leather
- ☑ Rain gear are made of polyurethane, PVC, vinyl, wax-coated or rubber
- ☑ Clothing has not been recently laundered with a fabric softener
- ☑ No coated HDPE suits (e.g., coated Tyvek® suits)
- ☑ Field crew has not used cosmetics, moisturizers, or other related products today
- ☑ Field crew has not used sunscreen or insect repellants today, other than products approved as PFAS-free

Field Equipment:

- ☑ Sample containers and equipment in direct contact with the sample are made of HDPE, polypropylene, silicone, acetate or stainless steel, not LDPE or glass
- ☑ Sample caps are made of HDPE or polypropylene and are not lined with Teflon™
- ☑ No materials containing Teflon™, Viton™, or fluoropolymers
- ☑ No materials containing LDPE in direct contact with the sample (e.g., LDPE tubing, Ziploc® bags)
- ☑ No plastic clipboards, binders, or spiral hard cover notebooks
- ☑ No waterproof field books
- ☑ No waterproof or felt pens or markers (e.g., certain Sharpie® products)
- ☑ No chemical (blue) ice, unless it is contained in a sealed bag
- ☑ No aluminum foil
- ☑ No sticky notes (e.g., certain Post-It® products)

Decontamination:

- ☑ Reusable field equipment (e.g., dip sampler) decontaminated prior to reuse
- ☑ "PFAS-free" water is on-site for decontamination of field equipment
- ☑ Alconox®, Liquinox® or Luminox® used as decontamination detergent

Food and Drink:

- ☑ No food or drink on-site, except within staging area
- ☑ Food in staging area is contained in HDPE or stainless steel container

Notes:

Waterproof boots worn without overboots

SOPs modified to no waterproof boots worn or overboots during surface water + sediment sampling

Field Team Leader Name (Print): Boone Abbott

Field Team Leader Signature: [signature]

Date/Time: 5-19-21 0713

## Attachment A. Daily Sampling Checklist

Date: 5-20-21

Site Name: Former FSPC

Weather (*temperature/precipitation*): Sunny 84°

**Please check all boxes that apply and describe any exceptions in the notes section below along with QA/QC methods used to assess potential sample cross-contamination as a result.**

Field Clothing and PPE:

- ☐ No water- or stain-resistant boots or clothing (e.g., GORE-TEX®) (not sediment or surface water sampling)
- ☐ Field boots (or overboots) are made of polyurethane, PVC, rubber, or untreated leather (not sediment or surface water sampling)
- ☑ Rain gear are made of polyurethane, PVC, vinyl, wax-coated or rubber
- ☑ Clothing has not been recently laundered with a fabric softener
- ☑ No coated HDPE suits (e.g., coated Tyvek® suits)
- ☑ Field crew has not used cosmetics, moisturizers, or other related products today
- ☑ Field crew has not used sunscreen or insect repellants today, other than products approved as PFAS-free

Field Equipment:

- ☑ Sample containers and equipment in direct contact with the sample are made of HDPE, polypropylene, silicone, acetate or stainless steel, not LDPE or glass
- ☑ Sample caps are made of HDPE or polypropylene and are not lined with Teflon™
- ☑ No materials containing Teflon™, Viton™, or fluoropolymers
- ☑ No materials containing LDPE in direct contact with the sample (e.g., LDPE tubing, Ziploc® bags)
- ☑ No plastic clipboards, binders, or spiral hard cover notebooks
- ☑ No waterproof field books
- ☑ No waterproof or felt pens or markers (e.g., certain Sharpie® products)
- ☑ No chemical (blue) ice, unless it is contained in a sealed bag
- ☑ No aluminum foil
- ☑ No sticky notes (e.g., certain Post-It® products)

Decontamination:

- ☑ Reusable field equipment (e.g., dip sampler) decontaminated prior to reuse
- ☑ "PFAS-free" water is on-site for decontamination of field equipment
- ☑ Alconox®, Liquinox® or Luminox® used as decontamination detergent

Food and Drink:

- ☑ No food or drink on-site, except within staging area
- ☑ Food in staging area is contained in HDPE or stainless steel container

Notes:

Waterproof boots worn with no overboots

SOPs modified for boots/overboots to include only surface water + sediment sampling

Field Team Leader Name (Print): Boone Abbott

Field Team Leader Signature: [signature]

Date/Time: 5-20-21 0720

## Attachment A. Daily Sampling Checklist

Date: 5-21-21

Site Name: Former FSFC

Weather (*temperature/precipitation*): Sunny 86°

**Please check all boxes that apply and describe any exceptions in the notes section below along with QA/QC methods used to assess potential sample cross-contamination as a result.**

Field Clothing and PPE:

- ☐ No water- or stain-resistant boots or clothing (e.g., GORE-TEX®) (Not sediment or surface water sampling)
- ☐ Field boots (or overboots) are made of polyurethane, PVC, rubber, or untreated leather (Not sediment or surface water sampling)
- ☑ Rain gear are made of polyurethane, PVC, vinyl, wax-coated or rubber
- ☑ Clothing has not been recently laundered with a fabric softener
- ☑ No coated HDPE suits (e.g., coated Tyvek® suits)
- ☑ Field crew has not used cosmetics, moisturizers, or other related products today
- ☑ Field crew has not used sunscreen or insect repellants today, other than products approved as PFAS-free

Field Equipment:

- ☑ Sample containers and equipment in direct contact with the sample are made of HDPE, polypropylene, silicone, acetate or stainless steel, not LDPE or glass
- ☑ Sample caps are made of HDPE or polypropylene and are not lined with Teflon™
- ☑ No materials containing Teflon™, Viton™, or fluoropolymers
- ☑ No materials containing LDPE in direct contact with the sample (e.g., LDPE tubing, Ziploc® bags)
- ☑ No plastic clipboards, binders, or spiral hard cover notebooks
- ☑ No waterproof field books
- ☑ No waterproof or felt pens or markers (e.g., certain Sharpie® products)
- ☑ No chemical (blue) ice, unless it is contained in a sealed bag
- ☑ No aluminum foil
- ☑ No sticky notes (e.g., certain Post-It® products)

Decontamination:

- ☑ Reusable field equipment (e.g., dip sampler) decontaminated prior to reuse
- ☑ "PFAS-free" water is on-site for decontamination of field equipment
- ☑ Alconox®, Liquinox® or Luminox® used as decontamination detergent

Food and Drink:

- ☑ No food or drink on-site, except within staging area
- ☑ Food in staging area is contained in HDPE or stainless steel container

Notes:

Waterproof boots worn w/o overboots

SOPs modified to only wear overboots/non-waterproof boots during sediment & surface water sampling

Field Team Leader Name (Print): Boone Abbott

Field Team Leader Signature: [signature]

Date/Time: 5-21-21 0734

## Attachment A. Daily Sampling Checklist

Date: 5-24-21

Site Name: Former Florida State Fire College

Weather (*temperature/precipitation*): Sunny 91°F

**Please check all boxes that apply and describe any exceptions in the notes section below along with QA/QC methods used to assess potential sample cross-contamination as a result.**

Field Clothing and PPE:

- ☐ No water- or stain-resistant boots or clothing (e.g., GORE-TEX®) (No sediment or surface water sampling)
- ☐ Field boots (or overboots) are made of polyurethane, PVC, rubber, or untreated leather
- ☑ Rain gear are made of polyurethane, PVC, vinyl, wax-coated or rubber
- ☑ Clothing has not been recently laundered with a fabric softener
- ☑ No coated HDPE suits (e.g., coated Tyvek® suits)
- ☑ Field crew has not used cosmetics, moisturizers, or other related products today
- ☑ Field crew has not used sunscreen or insect repellants today, other than products approved as PFAS-free

Field Equipment:

- ☑ Sample containers and equipment in direct contact with the sample are made of HDPE, polypropylene, silicone, acetate or stainless steel, not LDPE or glass
- ☑ Sample caps are made of HDPE or polypropylene and are not lined with Teflon™
- ☑ No materials containing Teflon™, Viton™, or fluoropolymers
- ☑ No materials containing LDPE in direct contact with the sample (e.g., LDPE tubing, Ziploc® bags)
- ☑ No plastic clipboards, binders, or spiral hard cover notebooks
- ☑ No waterproof field books
- ☑ No waterproof or felt pens or markers (e.g., certain Sharpie® products)
- ☑ No chemical (blue) ice, unless it is contained in a sealed bag
- ☑ No aluminum foil
- ☑ No sticky notes (e.g., certain Post-It® products)

Decontamination:

- ☑ Reusable field equipment (e.g., dip sampler) decontaminated prior to reuse
- ☑ "PFAS-free" water is on-site for decontamination of field equipment
- ☑ Alconox®, Liquinox® or Luminox® used as decontamination detergent

Food and Drink:

- ☑ No food or drink on-site, except within staging area
- ☑ Food in staging area is contained in HDPE or stainless steel container

Notes:

Waterproof boots worn with no overboots

SOPs modified to only need overboots for sediment/surface water sampling

Field Team Leader Name (Print): Boone Abbott

Field Team Leader Signature: [signature]

Date/Time: 5-24-21 1102

## Attachment A. Daily Sampling Checklist

Date: 5-25-21

Site Name: Former Florida State Fire College

Weather (*temperature/precipitation*): Sunny 93°F

**Please check all boxes that apply and describe any exceptions in the notes section below along with QA/QC methods used to assess potential sample cross-contamination as a result.**

Field Clothing and PPE:

No sediment or surface water sampling

- ☐ No water- or stain-resistant boots or clothing (e.g., GORE-TEX®)
- ☐ Field boots (or overboots) are made of polyurethane, PVC, rubber, or untreated leather
- ☑ Rain gear are made of polyurethane, PVC, vinyl, wax-coated or rubber
- ☑ Clothing has not been recently laundered with a fabric softener
- ☑ No coated HDPE suits (e.g., coated Tyvek® suits)
- ☑ Field crew has not used cosmetics, moisturizers, or other related products today
- ☑ Field crew has not used sunscreen or insect repellants today, other than products approved as PFAS-free

Field Equipment:

- ☑ Sample containers and equipment in direct contact with the sample are made of HDPE, polypropylene, silicone, acetate or stainless steel, not LDPE or glass
- ☑ Sample caps are made of HDPE or polypropylene and are not lined with Teflon™
- ☑ No materials containing Teflon™, Viton™, or fluoropolymers
- ☑ No materials containing LDPE in direct contact with the sample (e.g., LDPE tubing, Ziploc® bags)
- ☑ No plastic clipboards, binders, or spiral hard cover notebooks
- ☑ No waterproof field books
- ☑ No waterproof or felt pens or markers (e.g., certain Sharpie® products)
- ☑ No chemical (blue) ice, unless it is contained in a sealed bag
- ☑ No aluminum foil
- ☑ No sticky notes (e.g., certain Post-It® products)

Decontamination:

- ☑ Reusable field equipment (e.g., dip sampler) decontaminated prior to reuse
- ☑ "PFAS-free" water is on-site for decontamination of field equipment
- ☑ Alconox®, Liquinox® or Luminox® used as decontamination detergent

Food and Drink:

- ☑ No food or drink on-site, except within staging area
- ☑ Food in staging area is contained in HDPE or stainless steel container

Notes:

Waterproof boots worn with no overboots

SOPs modified to only wear overboots/non-waterproof boots during sediment & surface water sampling

Field Team Leader Name (Print): Boine Abbott

Field Team Leader Signature: [signature]

Date/Time: 5-25-21 0710

## Attachment A. Daily Sampling Checklist

Date: 5-26-21

Site Name: Former Florida State Fire College

Weather (*temperature/precipitation*): Sunny 95°F

**Please check all boxes that apply and describe any exceptions in the notes section below along with QA/QC methods used to assess potential sample cross-contamination as a result.**

Field Clothing and PPE:

No sediment or surface water sampling

- ☐ No water- or stain-resistant boots or clothing (e.g., GORE-TEX®)
- ☐ Field boots (or overboots) are made of polyurethane, PVC, rubber, or untreated leather
- ☑ Rain gear are made of polyurethane, PVC, vinyl, wax-coated or rubber
- ☑ Clothing has not been recently laundered with a fabric softener
- ☑ No coated HDPE suits (e.g., coated Tyvek® suits)
- ☑ Field crew has not used cosmetics, moisturizers, or other related products today
- ☑ Field crew has not used sunscreen or insect repellants today, other than products approved as PFAS-free

Field Equipment:

- ☑ Sample containers and equipment in direct contact with the sample are made of HDPE, polypropylene, silicone, acetate or stainless steel, not LDPE or glass
- ☑ Sample caps are made of HDPE or polypropylene and are not lined with Teflon™
- ☑ No materials containing Teflon™, Viton™, or fluoropolymers
- ☑ No materials containing LDPE in direct contact with the sample (e.g., LDPE tubing, Ziploc® bags)
- ☑ No plastic clipboards, binders, or spiral hard cover notebooks
- ☑ No waterproof field books
- ☑ No waterproof or felt pens or markers (e.g., certain Sharpie® products)
- ☑ No chemical (blue) ice, unless it is contained in a sealed bag
- ☑ No aluminum foil
- ☑ No sticky notes (e.g., certain Post-It® products)

Decontamination:

- ☑ Reusable field equipment (e.g., dip sampler) decontaminated prior to reuse
- ☑ "PFAS-free" water is on-site for decontamination of field equipment
- ☑ Alconox®, Liquinox® or Luminox® used as decontamination detergent

Food and Drink:

- ☑ No food or drink on-site, except within staging area
- ☑ Food in staging area is contained in HDPE or stainless steel container

Notes:

Waterproof boots with no overboots worn

SOPs modified to only wear overboots/non-waterproof during sediment + surface water sampling

Field Team Leader Name (Print): Boone Abbott

Field Team Leader Signature: [signature]

Date/Time: 5-26-21 0845

## Attachment A. Daily Sampling Checklist

Date: 5-27-21

Site Name: Former Florida State Fire College

Weather (*temperature/precipitation*): Sunny 91°F

**Please check all boxes that apply and describe any exceptions in the notes section below along with QA/QC methods used to assess potential sample cross-contamination as a result.**

Field Clothing and PPE:

- ☑ No water- or stain-resistant boots or clothing (e.g., GORE-TEX®) (No sediment or surface water sampling)
- ☑ Field boots (or overboots) are made of polyurethane, PVC, rubber, or untreated leather
- ☑ Rain gear are made of polyurethane, PVC, vinyl, wax-coated or rubber
- ☑ Clothing has not been recently laundered with a fabric softener
- ☑ No coated HDPE suits (e.g., coated Tyvek® suits)
- ☑ Field crew has not used cosmetics, moisturizers, or other related products today
- ☐ Field crew has not used sunscreen or insect repellants today, other than products approved as PFAS-free

Field Equipment:

- ☑ Sample containers and equipment in direct contact with the sample are made of HDPE, polypropylene, silicone, acetate or stainless steel, not LDPE or glass
- ☑ Sample caps are made of HDPE or polypropylene and are not lined with Teflon™
- ☑ No materials containing Teflon™, Viton™, or fluoropolymers
- ☑ No materials containing LDPE in direct contact with the sample (e.g., LDPE tubing, Ziploc® bags)
- ☑ No plastic clipboards, binders, or spiral hard cover notebooks
- ☑ No waterproof field books
- ☑ No waterproof or felt pens or markers (e.g., certain Sharpie® products)
- ☑ No chemical (blue) ice, unless it is contained in a sealed bag
- ☑ No aluminum foil
- ☑ No sticky notes (e.g., certain Post-It® products)

Decontamination:

- ☑ Reusable field equipment (e.g., dip sampler) decontaminated prior to reuse
- ☑ "PFAS-free" water is on-site for decontamination of field equipment
- ☑ Alconox®, Liquinox® or Luminox® used as decontamination detergent

Food and Drink:

- ☑ No food or drink on-site, except within staging area
- ☑ Food in staging area is contained in HDPE or stainless steel container

Notes:

No overboots / non-waterproof boots worn

SOPs modified to only wear overboots / non-waterproof boots during sediment or surface water sampling

Field Team Leader Name (Print): Boone Abbott

Field Team Leader Signature: [signature]

Date/Time: 5-27-21 0835

**Table 1: Proposed Sampling Locations, Matrices, Analytes, Rationale, and Criteria**
**Former Florida State Fire College**

| Location ID | Sample ID | Date and Time | Matrix | Depth (ft BLS) / Drilling Method | Comments |
|---|---|---|---|---|---|
| **Laboratory Quality Assurance/Quality Control Samples** | | | | | |
| **Sample Type** | **Sample ID** | **Date and Time** | **Matrix** | **Equipment sampled** | |
| Equipment Blanks (ratio of 1:10) | EQB-21 | 3-23-21 1410 | Water | DPT Groundwater Sampling Equipment | Boring before: SP-10 (80-90') Boring after: SP-14 (35-39') Container ID: 001036, 001112 |
| | EQB-22 | 3-24-21 0835 | | | Boring before: SP-14 (46-56') Boring after: SP-8 (32-36') Container ID: 001105, 001112 |
| | EQB-23 | 3-29-21 1445 | | | Boring before: SP-3 (86-90') Boring after: SP-5 (46-50') Container ID: 000884 |
| | EQB-24 | 3-30-21 1405 | | | Boring before: SP-11 (30-35') Boring after: SP-25 (66-70') Container ID: 000884 |
| | EQB-25 | 3-31-21 1347 | | | Boring before: SP-22 (46-50') Boring after: SP-17 (36-40') Container ID: 000852, 000884 |
| | EQB-26 | 4-2-21 0916 | | | Boring before: SP-13 (36-40') Boring after: SP-21 (40-50') Container ID: 000605 |
| | EQB-27 | 4-5-21 1541 | | | Boring before: SP-23 (36-40') Boring after: SP-19 (36-40') Container ID: 000335 |
| | EQB-28 | 4-6-21 1308 | | | Boring before: SP-18 (46-50') Boring after: SP-16 (36-40') Container ID: 000866, 000838 |
| | EQB-29 | 3-22-21 1355 | | Soil Sampling Equipment Hand Auger | Boring before: SB-62 (0-0.5') Boring after: SB-57 (0-0.5') Container ID: 001036 |
| | EQB-30 | 3-23-21 0910 | | | Boring before: SB-64 (4-6') Boring after: SB-8 (2-4') Container ID: 001036 |
| | EQB-31 | 3-23-21 1100 | | | Boring before: SB-10 (4-6') Boring after: SB-66 (2-4') Container ID: 001036 |
| | EQB-32 | 3-23-21 1510 | | | Boring before: SB-67 (4-6') Boring after: SB-45 (4-6') Container ID: 001013 |
| | EQB-33 | 3-24-21 1030 | | | Boring before: SB-37 (4-6') Boring after: SB-70 (0-0.5') Container ID: 001046 |
| | EQB-34 | 3-24-21 1035 | | | Boring before: SB-73 (2-4') Boring after: SB-70 (2-4') Container ID: 001046 |
| | EQB-35 | 3-24-21 1150 | | | Boring before: SB-70 (0-0.5') Boring after: SB-69 (0-0.5') Container ID: 001046 |
| | EQB-36 | 3-24-21 1155 | | | Boring before: SB-70 (2-4') Boring after: SB-69 (2-4') Container ID: 001046 |
| | EQB-37 | 3-24-21 0838 | | Soil Sampling Equipment DPT | Boring before: SB-68 (5-10') Boring after: SB-45 (5-10') Container ID: 001105 |
| | EQB-38 | 3-24-21 0840 | | | Boring before: SB-68 (10-15') Boring after: SB-45 (10-15') Container ID: 001105 |
| | EQB-39 | 3-24-21 1230 | | | Boring before: SB-45 (30-35') Boring after: SB-72 (10-15') Container ID: 000866 |
| | EQB-40 | 5-19-21 1236 | | MW Installation Equipment | Boring before: DEPMW-2 (25-45') Boring after: DEPMW-3 (100-120') Container ID: 000206 |
| | EQB-41 | 5-24-21 1206 | | | Boring before: DEPMW-5 (100-120') Boring after: DEPMW-6 (25-45') Container ID: 000273 |
| | EQB-42 | | | Submersible Pump | Boring before: Boring after: Container ID: |
| Field Reagent Blanks | FRB-4 | 3-24-21 1011 | | DPT Groundwater Sampling | 001062 |
| | FRB-5 | | | Groundwater Sampling | |
| | FRB-6 | 3-24-21 0900 | | HA+DPT Decontamination | 001105, 001062 |
| | FRB-7 | 5-19-21 1240 | | MW Decon ~~MW Sampling~~ | 000273 |
| | FRB-8 | | | Extra | |
| **IDW Samples** | | | | | |
| **Drum Number** | **Sample ID** | | **Matrix** | **IDW Source** | **Analyses** |
| | IDW-Soil-202103__ | | Soil | Soil cuttings | PFAS, VOCs, SVOCs, 8 RCRA Metals |
| | IDW-Water-202103__ | | Water | Decontamination and purge water | |

Notes:
1. DPT indicates direct push technology
2. ft BLS indicates feet below land surface
3. SB indicates soil boring
4. HA indicates hand auger
5. PFAS indicates per- and polyfluoroalkyl substances
6. N/A indicates not applicable.
7. EQB indicates equipment blank
8. SP indicates screen point.
9. EQB indicates equipment blank
10. FRB indicates field reagent blank
11. MW indicates monitoring well

# Geosyntec consultants

## Boring Log

Boring No.: DEPMW-1 (100-120') Project No.: FR7522A.01.04 Page 1 of 3
Site: Former Florida State Fire College Date: 5-17-21
Tools and Method: Sonic Bit Dia.: 4"
Total Depth: 120 ft Ground Elev.: - Groundwater Depth: ~34 ft
Drilling Company: Preferred Drilling Solutions Rig: 815OLS
Driller: Kent Fowler Logger: Boone Abbott Reviewer:

Borehole Location Map


Boring: DEPMW-1 (100-120') Proj.No.: FR7522A.01.04 Site: Former Florida State Fire College Page 1 of 3

| Elev. (feet) | Top (Feet) | Lithology Log | Graphic Log | Depth Scale | Std. Pen. Test Blows /6" | Run/Rec. | N | Drilling Log |
|---|---|---|---|---|---|---|---|---|
| | | 0-0.5: silty SAND (SM), brown-dark brown, roots/rootlets, organic material, loose, some cohesive nodules, very fine-fine, dry | SM | | | | | Begun drilling 1700 |
| | 0-5 HA | 0.5-5: SAND (SP) light brown, loose, fine grained, dry uniform, poorly graded | SP | | | 5/5 | | HA - 0-5 ft |
| 5 | | | | | | | | Sonic starting at 5 ft |
| | 5-10 Sonic | 5-11: Clayey SAND (SC), reddish brown, slightly cohesive, very fine-fine, low plasticity, dry | SC | | | 5/3 | | |
| 10 | | | | | | | | 1711 4" to 10' |
| | | 11-11.5: SAND (SP), light brown, loose, fine grained, dry, poorly graded | SC / SP | | | | | 1746 6" to 10' |
| | | 11.5-13.5: Clayey SAND (SC), reddish brown, slightly cohesive, very fine-fine, low plasticity, dry | SC | | | | | 1800 8" to 10' |
| 15 | 10-20 Sonic | 13.5-20: SAND (SP), light brown, loose, fine grained, dry, poorly graded | SP | | | 10/8 | | |
| 20 | | 20-22: Clayey SAND (SC), reddish brown, slightly cohesive, very fine-fine, low plasticity, dry | SC | | | | | 1719 4" to 20' |
| | | 22-23: SAND (SP), light brown, loose fine grained, dry, poorly graded | SP | | | | | 1748 6" to 20' |
| | | 23-30: Sandy CLAY (CL), light brown-brown, cohesive, very fine-fine, low plasticity, dry, medium density | | | | | | 50 gallons used to drill 6" from 10-20' |
| 25 | 20-30 sonic | 25: Layer of SP (2") | CL | | | 10/8 | | 1802 8" to 20' |
| | | 27: medium plasticity, purple mottling | | | | | | |
| 30 | | 30-34: Clayey SAND (SC), reddish brown, slightly cohesive-cohesive, very fine-fine, low plasticity, dry | SC | | | | | 1726 4" to 30' |
| | | ▽ | | | | | | 1750 6" to 30' |
| | | | | | | | | 1804 8" to 30' |
| 35 | 30-40 sonic | 34-47: LIMESTONE, white/cream, friable, wet, marly, fossiliferous, strong, Wackestone and increasing in grain content to Packstone, cemented disks present | LS | | | 10/10 | | rig chatter, broke a rod, threads snapped on 4" |
| 40 | | | | | | | | 1741 4" to 40' |
| | | | | | | | | 1752 6" to 40' - 50 gallons used to drill 6" from 20-40' |
| | | | | | | | | 1806 8" to 40' 260 gallons used to drill 8" from 0-40' |
| | | | | | | | | end drilling on 5-17-21 |

the rest of 30-40' core was pulled out on 5-18-21

Geosyntec consultants

Boring Log

Boring No.: DEPMW-1 (100-120') Site: former FSFC Proj. No.: FR7522A.01.04 Page 2 of 3

| Elev. (feet) | Top (Feet) | Lithology Log | Graphic Log | Depth Scale | Std. Pen. Test Blows/6" | Run/Rec. | N | Drilling Log |
|---|---|---|---|---|---|---|---|---|
| 40 | | 34-47: LIMESTONE, white/cream, friable, wet, marly, fossiliferous, Wackestone → Packstone, strong | | | | | | Began drilling 5-18-21<br>Pulled at rest at 30-40' first then did a 20 ft run |
| 45 | | | | | | | | |
| 50 | 40-60 Sonic Run | 47-80: Sandy LIMESTONE, white - pale brown, wet, marly, fine grained, loosely cemented with some cemented disks, vugs present in cemented fragments, fossiliferous, cemented fragments are strong, Wackestone/Packstone | | | | 20/16 | | 0752 4" to 50'<br>0758 6" to 50' |
| 55 | | | | | | | | |
| 60 | | | | | | | | 0755 4" to 60'<br>0801 6" to 60'<br>100 gallons used from 40-60' |
| 65 | | | | | | | | |
| 70 | 60-80 Sonic Run | | | | | 20/18 | | 0802 4" to 70'<br>0808 6" to 70' |
| 75 | | | | | | | | |
| 80 | | 80-88: Dolomitic LIMESTONE, white - pale brown, marly, fine grained - microcrystalline, very strong, competent sections up to 6", wet | | | | | | 0805 4" to 80'<br>0810 6" to 80'<br>100 gallons used from 60-80' |
| 85 | 80-100 Sonic Run | | | | | 20/18 | | rig chatter<br>significantly longer to drill 80-90' |
| 90 | | 88-120: Sandy LIMESTONE, white - pale brown, wet, marly, fine grained, fossiliferous, loosely cemented with some cemented disks, vugs present in cemented fragments, Wackestone - Packstone | | | | | | 4" to 90' at 0832<br>6" to 90' at 0849 |

Boring: DEPMW-1 (100-120') Site: former FSFC Proj.No.: FR7522A.01.04 Page 2 of 3

Geosyntec consultants

Boring Log

Boring No.: DEPMW-1 (100-128) Site: Former FSFC Proj. No.: FR7522A.01.04 Page 3 of 3

| Elev. (feet) | Top (Feet) | Lithology Log | Graphic Log | Depth Scale | Std. Pen. Test Blows/6" | Run/Rec. | N | Drilling Log |
|---|---|---|---|---|---|---|---|---|
| 90 | | 88-120. Sandy LIMESTONE, while pale brown, wet, marly, fine grained, fossiliferous, loosely cemented with some cemented fragments, vugs + shelltex shell impressions present, leps present, Wackestone: Packstone | | | | | | 4" to 90' at 0832<br>6" to 90' at 0849 |
| 95 | 80-100 Sonic Run | | | | | 20/18 | | |
| 100 | | leps, shell fragments, vugs present in two 4" cemented disks at 100' | | | | | | 4" to 100' at 0845<br>6" to 100' at 0855<br>150 gallons used 80-100' |
| 105 | | | | | | | | |
| 110 | | | | | | 20/13 | | 4" to 110' at 0908<br>6" to 110' at 0920 |
| 115 | | | | | | | | |
| 120 | | boring ended | | | | | | 4" to 120' at 0914<br>6" to 120' at 0925<br>100 gallons used 100-120'<br>17 bags of 20/30 sand were used and would not come up past 115'. PDS goes to get pea gravel.<br>77 bags of pea gravel used.<br>4 more bags of 20/30 (21 total) used to get to 98 ft bls. |

Boring: DEPMW-1 (100-120') Site: Former FSFC Proj.No.: FR7522A.01.04 Page 3 of 3

# Geosyntec consultants

## Boring Log

Boring No.: DEPMW-3 (100-128) Project No.: FR7522A.01.04 Page 1 of 3

Site: Former Florida State Fire College (FFSFC) Date: 5-19-21

Tools and Method: Sonic Bit Dia.: 4"

Total Depth: _____ Ground Elev.: _____ Groundwater Depth: _____

Drilling Company: Preferred Drilling Solutions Rig: 8150 LS - Geoprobe

Driller: Kent Fowler Logger: Boone Abbott Reviewer: _____

Borehole Location Map




Boring: DEPMW-3 (100-128) Site: FFSFC Proj.No.: FR7522A.01.04 Page 1 of 3

| Elev. (feet) | Top (Feet) | Lithology Log | Graphic Log | Depth Scale | Std. Pen. Test Blows /6" | Run/Rec. | N | Drilling Log |
|---|---|---|---|---|---|---|---|---|
| | 0-5 HA | 0-0.5: Silty SAND (SM), brown-dark brown, rootlets, organic material, loose, some cohesive pods, very fine-fine, dry | SM | | | | | Begin drilling 1500 |
| | | 0.5-5: SAND (SP), light brown, loose, dry, very fine-fine, uniform, poorly graded | SP | | | 5/5 | | HA 0-5 ft |
| 5 | | | | | | | | Sonic starting at 5 ft |
| | 5-20 Sonic Run | 5-22 Clayey SAND (SC), reddish brown, cohesive, very fine-fine, low plasticity, dry | | | | | | |
| 10 | | 10-22: SAA, grey-pale brown, orange mottling, dark brown nodules present | SC | | | 15/12 | | 1520 4" to 10' |
| | | | | | | | | 1538 6" to 10' |
| | | | | | | | | 1545 8" to 10' |
| 15 | | | | | | | | |
| 20 | | | | | | | | 1523 4" to 20' |
| | | 22-27.5: Sandy CLAY, greenish grey, very fine-fine, medium-high plasticity, medium density | SC | | | | | 1540 6" to 20' |
| | 20-30 Sonic Run | | SC | | | | | 1550 8" to 20' |
| 25 | | | | | | 10/10 | | |
| | | 27.5-28.0: SAND (SP), pale brown, very fine-fine, uniform, loose, dry (moisture could have evaporated by heat of drilling) | | | | | | |
| | | ~~28: Clayey SAND (SC), pale brown-light brown~~ | | | | | | |
| 30 | | 28-29: LIMESTONE, grey-pale brown, crystalline, strong-very strong, fossiliferous, fine, cherty | | | | | | 1534 4" to 30' |
| | | 29-34: Clayey SAND (SC), reddish brown-pale brown, cohesive, soft, medium plasticity with abundant interbedded chert, wet, orange mottling | | | | | | 1543 6" to 30' |
| | | | | | | | | 100 gal used to drill 4" + 6" to 30' |
| | | | | | | | | 1553 8" to 30' |
| | | | | | | | | 200 gallons used to drill 8" to 30' |
| 35 | | 34-80: LIMESTONE, ~~yellowish brown~~-pale brown, fossiliferous, friable, very soft-soft, loosely cemented, some cemented fragments, wet, wackestone, Marly | | | | 10/10 | | |
| | 30-40 Sonic Run | | | | | | | |
| 40 | | | | | | | | 1555 4" to 40' |
| | | | | | | | | 1557 6" to 40' |
| | | | | | | | | 1600 8" to 40' |

Geosyntec consultants

Boring Log

Boring No.: DEPMW-3 (100-120') Site: FFSFC Proj. No.: FR7522A.01.04 Page 2 of 3

Boring: DEPMW-3 (100-120') Site: FFSFC Proj.No.: FR7522A.01.04 Page 2 of 3

| Elev. (feet) | Top (Feet) | Lithology Log | Graphic Log | Depth Scale | Std. Pen. Test Blows/6" | Run/Rec. | N | Drilling Log |
|---|---|---|---|---|---|---|---|---|
| 90 | | | | | | | | 1555 4" to 46'<br>1557 6" to 46'<br>1600 8" to 40' - pulled sample |
| | | | | | | | | Driller noted soft from 40-80 |
| 45 | | | | | | | | |
| 50 | | | | | | | | 1610 4" to 50'<br>1621 6" to 50' |
| 55 | | | | | | | | |
| 60 | | | | | | 50/ 40 | | 1612 4" to 60'<br>1622 6" to 60' |
| | 40 - 90 Sonic Run | 65-68: yellowish brown staining | | | | | | |
| 65 | | | | | | | | |
| 70 | | | | | | | | 1614 4" to 70'<br>1623 6" to 80' |
| 75 | | 76-77: yellowish brown staining | | | | | | |
| 80 | | 80-90: No recovery | | | | | | 1615 4" to 86'<br>Rod dropped 5-6 ft from 80-85/86'<br>1624 6" to 80' |
| 85 | | | | | | | | Driller noted very soft |
| 90 | | | | | | | | 1619 4" to 90' - pulled cores 40-90'<br>1625 6" to 90' |

Geosyntec consultants

Boring Log

Boring No.: DEPMW-3 (100-120') Site: FFSFC Proj. No.: FR7522A.01.04 Page 3 of 3

| Elev. (feet) | Top (Feet) | Lithology Log | Graphic Log | Depth Scale | Std. Pen. Test Blows/6" | Run/Rec. | N | Drilling Log |
|---|---|---|---|---|---|---|---|---|
| 90 | | 90-92: Shell hash, very fossiliferous, wet | | | | | | 1619 4" to 90' [redacted] 6" to 90' 1625 |
| | | 92-94: Clayey SAND, grey, purple staining, orange mottling, very fine-medium, shell fragments present wet, cohesive | | | | | | |
| 95 | | 94-96: LIMESTONE, pale brown, friable, fossiliferous, cemented fragments, wet, wackestone / Packstone, | | | | | | |
| | | 96-105: Clayey SAND (SC), grey, purple staining, (greenish grey - high plasticity) orange mottling nodules, medium plasticity, wet, cohesive | | | | | | |
| 100 | | 90-120 Sonic Run | | | | | | 1642 4" to 100' 1646 6" to 100' |
| | | | | | | 30/30 | | |
| 105 | | 105-118: Marly Dolomitic LIMESTONE, strong, grey-brown, fossiliferous, wet, organic odor, friable with competent cemented sections (disks), recrystallized nodules, | | | | | | driller noted more competent |
| 110 | | | | | | | | 1643 4" to 110' 1649 6" to 110' |
| 115 | | | | | | | | |
| | | 118-120: [redacted] dolomitic LIMESTONE, very strong, brown, cemented, recrystallized, fossiliferous | | | | | | rig chatter 1644 4" to 120' 1651 6" to 120' |
| 120 | | boring ended | | | | | | 350 gal used to drill from 30-120' |

Boring: DEPMW-3 (100-120') Site: FFSFC Proj.No.: FR7522A.01.04 Page 3 of 3

J:/FLWP/DAS/BORING LOGS/BORINGLOG.CDR (PDF)

# Geosyntec consultants

## Boring Log

Borehole Location Map

Boring No.: DEPMW-5 (100-120') Project No.: FR75221.01.04 Page 1 of 3

Site: Former Florida State Fire College Date: 5-21-21

Tools and Method: Sonic Bit Dia.: 4"

Total Depth: 120' Ground Elev.: ____ Groundwater Depth: ~35 ft

Drilling Company: Preferred Drilling Solutions Rig: Geoprobe 8150LS

Driller: Kent Fowler Logger: Boone Abbott Reviewer: ____

Page 1 of 3 | Proj.No.: FR75221.01.04 | Site: FFSFC | Boring: DEPMW-5 (100-120')

| Elev. (feet) | Top (Feet) | Lithology Log | Graphic Log | Depth Scale | Std. Pen. Test Blows /6" | Run/Rec | N | Drilling Log |
|---|---|---|---|---|---|---|---|---|
| | 0-5 HA | 0-0.5: Silty SAND (SM), dark brown, loose, very fine-fine, organic material, dry, rootlets | SM | | | | | Begin drilling 5-21-21<br>0-5 HA - hand auger<br>Begin sonic at 5' bls |
| | | 0.5-10: ~~SAND (SC)~~ clayey SAND (SC), reddish brown, loose with cohesive peds, very fine-fine, dry | SC | | | 5/5 | | |
| 5 | | | | | | | | |
| | | 6: white/grey calc 2-3" | | | | | | |
| | | | SC | | | | | |
| | | 9: SAA: grey, cohesive | | | | | | |
| 10 | 5-20 Sonic Run | 10-20: No recovery | | | | 15/5 | | 0816 4" to 10'<br>0849 6" to 10'<br>0905 8" to 10' |
| 15 | | | | | | | | |
| 20 | | | | | | | | 0819 4" to 20'<br>0853 6" to 20'<br>0911 8" to 20' |
| | | | | | | | | Driller noted that this section felt like dense clay until 35 ft where rig chatter occurred, b/c of this comment + the surrounding area, BA logged the recovered material at 35'. |
| 25 | | | | | | | | |
| | | | | | | 20/5 | | |
| 30 | 20-40 Sonic Run | | | | | | | 0825 4" to 30'<br>0855 6" to 30'<br>0916 8" to 30' |
| | | | ▽ | | | | | |
| 35 | | 35-120: LIMESTONE, white/cream, wet, friable, horizontally bedded based on fracture planes, loosely cemented with some cemented chunks, fossiliferous, wackestone, sandy, marly | | | | | | rig chatter |
| 40 | | | | | | | | 0834 4" to 40'<br>0859 6" to 40'<br>0918 8" to 40'<br>500 gallons used 5-40' |

Geosyntec consultants

Boring Log

Boring No.: DEPMW-5(100-120') Site: FFSFC Proj. No.: FR7522A.01.04 Page 2 of 3

| Elev. (feet) | Top (Feet) | Lithology Log | Graphic Log | Depth Scale | Std. Pen. Test Blows/6" | Run/Rec. | N | Drilling Log |
|---|---|---|---|---|---|---|---|---|
| 40 | | | | | | | | 0834 4" to 40'<br>0859 6" to 40'<br>0918 8" to 40'<br>500 gallons used 5-40' |
| 45 | | 47-49: yellowish brown, loosely cemented, no fossils, mudstone | | | | | | |
| 50 | | 49-80: fossiliferous, limestone, some cemented fragments, pale brown-very pale brown | | | | | | 0923 4" to 50'<br>0930 6" to 50' |
| 55 | | | | | | 40/39 | | |
| 60 | 40 - 80 Sonic Run | | | | | | | 0925 4" to 60'<br>0931 6" to 60' |
| 65 | | | | | | | | |
| 70 | | | | | | | | 0926 4" to 70'<br>0932 6" to 70' |
| 75 | | | | | | | | |
| 80 | | 80-85: LIMESTONE, mudstone, slightly cemented-cemented, marly, clay-like, soft, pale brown | | | | | | 0928 4" to 80'<br>0933 6" to 80'<br>100 gal used from 40-80' |
| 85 | 80-100 Sonic Run | 85-100: SAA, limestone, cemented, friable, pale brown, fossiliferous, marly | | | | 20/14 | | rig chatter |
| 90 | | | | | | | | 0954 4" to 90'<br>1009 6" to 90' |

Boring: DEPMW-5 (100-120') Site: FFSFC Proj.No.: FR7522A.01.04 Page 2 of 3

Geosyntec consultants

Boring Log

Boring No.: DEPMW-5 (100-120') Site: FFSFC Proj. No.: FR7522A.01.04 Page 3 of 3

| Elev. (feet) | Top (Feet) | Lithology Log | Graphic Log | Depth Scale | Std. Pen. Test Blows/6" | Run/Rec. | N | Drilling Log |
|---|---|---|---|---|---|---|---|---|
| 90 | | LIMESTONE, wackestone, pale brown, fossiliferous, wet, marly, cemented gravel, friable | | | | | | 0954 4" to 90' |
| | 80-100 Sonic Run | | | | | | | 1009 6" to 90' |
| 95 | | | | | | 20/14 | | |
| 100 | | | | | | | | 1000 4" to 100' |
| | | | | | | | | 1012 6" to 100' |
| | | | | | | | | 150 gal used 80-100' |
| 105 | | 105-106: yellowish, reddish brown | | | | | | |
| | 100-120 Sonic Run | | | | | | | |
| 110 | | 110-120: gray, dolomitic | | | | 20/14 | | 1032 4" to 110' |
| | | | | | | | | 1038 6" to 120' |
| 115 | | | | | | | | |
| 120 | | boring ended | | | | | | 1035 4" to 120' |
| | | | | | | | | 1040 6" to 120' |
| | | | | | | | | 150 gallons used 100-120' |

Boring: DEPMW-5 (100-120') Site: FFSFC Proj.No.: FR7522A.01.04 Page 3 of 3

J:/FLWP/DAS/BORING LOGS/BORINGLOG.CDR (PDF)

# Geosyntec consultants

## Boring Log

Borehole Location Map

Boring No.: DEPMW-7 (100-120') Project No.: FR7522A.01.04 Page 1 of 3

Site: Former Florida State Fire College Date: 5-25-21

Tools and Method: Sonic Bit Dia.: 4"

Total Depth: 120' Ground Elev.: ____ Groundwater Depth: ~30 ft

Drilling Company: Preferred Drilling Solutions Rig: Geoprobe 8150LS

Driller: Kent Fowler Logger: Boone Abbott Reviewer: ____

Page 1 of 3 | Proj.No.: FR7522A.01.04 | Site: FFSFC | Boring: DEPMW-7 (100-120')

| Elev. (feet) | Top (Feet) | Lithology Log | Graphic Log | Depth Scale | Std. Pen. Test Blows /6" | Run/Rec. | N | Drilling Log |
|---|---|---|---|---|---|---|---|---|
| | | 0-0.5-5: silty SAND (SM) light brown-dark brown, loose, dry, organic material, rootlets, very fine-fine | SM | | | | | Begin drilling 5-25-21 |
| | 0-5 HA | 0.5-3: SAND (SP), light brown, loose, dry, very fine-fine | SP | | | 5/5 | | 0-5 Hand auger (HA) |
| | | 3-7: Clayey SAND (SC), light brown-grey, orange mottling, cohesive, medium density, low plasticity, very fine | SC | | | | | Begin sonic at 5' bls - 0745 |
| 5 | | | | | | | | |
| | | 7-30: Sandy CLAY (CL) grey-greenish grey, cohesive, orange mottling, medium plasticity, dense, very fine sand, intermittent chert pieces (1"-gravel size) | SC | | | | | |
| 10 | 5-20 Sonic Run | | | | | 15/8 | | 0754 4" to 10' |
| | | | | | | | | 0807 6" to 10' |
| | | | | | | | | 0816 8" to 10' |
| 15 | | | CL | | | | | |
| 20 | | | | | | | | 0755 4" to 20' |
| | | | | | | | | 0808 6" to 20' |
| | | | | | | | | 0819 8" to 20' |
| 25 | | | CL | | | | | |
| | | 27-30: SAA soft, high plasticity | | | | | | |
| 30 | | 30-120: LIMESTONE, very pale brown-white/cream, wet, friable, loosely cemented with some cemented disks, marly, fossiliferous, horizontally bedded based on fracture planes (disks), wackestone | | | | 20/20 | | 0801 4" to 30' |
| | | | | | | | | 0809 6" to 30' |
| | | | | | | | | 0821 8" to 30' |
| 35 | 20-40 Sonic Run | 34: 4" cemented core | LS | | | | | |
| | | 38-40: lovely cemented, no fossils or cemented fragments, Mudstone | | | | | | |
| 40 | | | | | | | | 0804 4" to 40' |
| | | | | | | | | 0811 6" to 40' |
| | | | | | | | | 0823 8" to 40' |
| | | | | | | | | 300 gal used 0-40' |

Geosyntec consultants

Boring Log

Boring No.: DEPMW-7(100-120') Site: FFSFC Proj. No.: FR7522A.01.04 Page 2 of 3

| Elev. (feet) | Top (Feet) | Lithology Log | Graphic Log | Depth Scale | Std. Pen. Test Blows/6" | Std. Pen. Test Run/Rec. | Std. Pen. Test N | Drilling Log |
|---|---|---|---|---|---|---|---|---|
| 40 | | 30-110: LIMESTONE, very pale brown-white/cream, wet, friable, loosely cemented with some cemented disks, marly, fossiliferous, horizontally bedded based on fracture planes (disks), packstone | | | | | | 0804 4" to 40'<br>0811 6" to 40'<br>0823 8" to 40'<br>300 gal used 0-40' |
| 45 | | | | | | | | |
| 50 | | | | | | | | 0834 4" to 50'<br>0841 6" to 50' |
| 55 | | | | | | | | |
| 60 | 40 - 80 Sonic Run | | LS | | | 40/40 | | 0835 4" to 60'<br>0893 6" to 60' |
| 65 | | | | | | | | |
| 70 | | | | | | | | 0837 4" to 70'<br>0844 6" to 70' |
| 75 | | 75-80: SAND, loosely cemented, marly, no cemented fragments or fossils, mudstone, clay-like - cohesive | | | | | | |
| 80 | | | | | | | | 0838 4" to 80'<br>0846 6" to 80'<br>150 gals used 40-80'<br>rig chatter |
| 85 | 80-120 Sonic Run | | LS | | | 40/24 | | |
| 90 | | | | | | | | 0902 4" to 90'<br>0920 6" to 90' |

Boring: DEPMW-7 (100-120') Site: FFSFC Proj.No.: FR7522A.01.04 Page 2 of 3

Geosyntec consultants

Boring Log

Boring No.: DEPMW-7 (100-120') Site: FFSFC Proj. No.: FR7522A.01.04 Page 3 of 3

| Elev. (feet) | Top (Feet) | Lithology Log | Graphic Log | Depth Scale | Std. Pen. Test Blows/6" | Run/Rec. | N | Drilling Log |
|---|---|---|---|---|---|---|---|---|
| 90 | | 90-120 LIMESTONE, very pale brown - white/cream, wet, friable, loosely cemented with some cemented disks, marly, fossiliferous, horizontally bedded based on fracture planes (disks), wackestone | | | | | | 0902 4" to 90'<br>0920 6" to 90' |
| | | 94-98: SAA, mudstone, cohesive clay-like, marly, orangish mottling, dry but could be from evaporation, no cemented fragments, slightly cemented matrix | | | | | | rig chatter |
| 95 | | | | | | | | rig chatter |
| 100 | | | | | | | | 0910 4" to 100'<br>0923 6" to 100' |
| | 80 - 120 Sonic Run | | LS | | | 40/24 | | Driller noted softer beneath 100 ft bls |
| 105 | | | | | | | | |
| 110 | | | | | | | | 0914 4" to 110'<br>0925 6" to 110' |
| 115 | | | | | | | | [illegible] |
| 120 | | boring ended | | | | | | 0916 4" to 120'<br>0930 6" to 120'<br>300 gal used 80-120' |

Boring: DEPMW-7 (100-120') Site: FFSFC Proj.No.: FR7522A.01.04 Page 3 of 3

# WELL CONSTRUCTION LOG
# STANDARD FLUSH MOUNT

Well I.D.: DEPMW-1 (100-120')
Drilling Company: Preferred Drilling Solutions (PDS)
Driller(s): Kent Fowler
Geologist/Eng./Tech.: Boone Abbott
Signature:

Site: Former Florida State Fire College
Project Number: FR 7522A.01.04
Installation Method: Sonic
Casing Installation Date: 5-18-21
Well Type: Groundwater Monitoring
Well Completion Method: Flush Mount




**Well Completion**
Guard Posts ( Y / (N) ) Date: 5-27-21
Surface Pad Size: 2 ft x 2 ft

**Protective Casing or Cover**
Diameter/Type: 8" steel manhole
Depth BGS: 12" Weep Hole ( Y / (N) )

**Grout**
Composition/Proportions: Portland Type I/II
4 bags per batch x 6 batches = 24 bags total
Placement Method: Tremie Pipe

**Seal** Date: 5-18-21
Type: Bentonite
Source: 1 Hole-Plug
Set-up/Hydration Time: 1 hour
Placement Method: Direct Pour
Vol. Fluid Added: N/A

**Filter Pack**
Type: 20/30 sand + Pea Gravel
Source: Standard Sand+Silica Co.
Amount Used: 21 bags 20/30 + 77 bags Pea gravel
Placement Method: Direct Pour

**Well Riser Pipe**
Casing Material: 2" PVC
Casing Inside Diameters: 2" in.

**Screen**
Material: PVC
Inside Diameter: 2" in.
Screen Slot Size:: 0.010 in.
Percent Open Area: -
Sump or Bottom Cap (Y / N)
Type/Length: Bottom Cap / 4.5"

**Total Water Volume During Construction**
Introduced (Gal): 750
Recovered (Gal): 165

**Reviewed**
By: _____ Date: _____

**Comments**

cap = 4.5" = 0.375'
screen = 9.9583'
risers = 10.0'

Void encountered at ~115 ft bls, 77 bags of pea gravel were used to fill void
Surface casing (8") was drilled to 40' bls to seal off unit above limestone
Apparent water level based on soil cores ~34 ft bls, measured WL on 5-19-21 = 31.16 ft below TOC
5-19-21: 2 more batches of grout (6 total batches) + 20 bags of pea gravel (97 total) were used to get the grout back up (it dropped overnight significantly)

# WELL CONSTRUCTION LOG
# STANDARD FLUSH MOUNT

Well I.D.: DEPMW-2 (25-45')
Drilling Company: Preferred Drilling Solutions (PDS)
Driller(s): Kent Fowler
Geologist/Eng./Tech.: Boone Abbott
Signature: [signature]

Site: Former Florida State Fire College
Project Number: FR7522A.01.04
Installation Method: Sonic
Casing Installation Date: 5-19-21
Well Type: Groundwater Monitoring
Well Completion Method: Flush Mount




**Comments**

**Well Completion**
Guard Posts ( Y / (N) ) Date: 5-27-21
Surface Pad Size: 2 ft x 2 ft

**Protective Casing or Cover**
Diameter/Type: 8" steel manhole
Depth BGS: 12" Weep Hole ( Y / (N) )

**Grout**
Composition/Proportions: Portland Type I/II
4 bags per batch x2.5 batches = 10 bags
Placement Method: Tremie pipe / Direct Pour

**Seal** Date: 5-19-21
Type: 30/65 Sand
Source: Standard Sand + Silica Co.
Set-up/Hydration Time: N/A
Placement Method: Direct Pour
Vol. Fluid Added: N/A

**Filter Pack**
Type: 20/30 Sand
Source: Standard Sand + Silica Co.
Amount Used: 10 bags
Placement Method: Direct Pour

**Well Riser Pipe**
Casing Material: PVC
Casing Inside Diameters: 2 in.

**Screen**
Material: PVC
Inside Diameter: 2 in.
Screen Slot Size:: 0.010 in.
Percent Open Area: -
Sump or Bottom Cap ( (Y) / N )
Type/Length: Bottom Cap / 4.5"

**Total Water Volume During Construction**
Introduced (Gal): 400
Recovered (Gal): 165

**Reviewed**
By: _____ Date: _____

# WELL CONSTRUCTION LOG
# STANDARD FLUSH MOUNT

Well I.D.: DEPMW-3 (100-120')
Drilling Company: Preferred Drilling Solutions
Driller(s): Kent Fowler
Geologist/Eng./Tech.: Boone Abbott
Signature:

Site: Former Florida State Fire College
Project Number: FR7522A.01.04
Installation Method: Sonic
Casing Installation Date: 5-19-21
Well Type: Groundwater Monitoring
Well Completion Method: Flush Mount




**Well Completion**
Guard Posts ( Y / (N) ) Date: 5-27-21
Surface Pad Size: 2 ft x 2 ft

**Protective Casing or Cover**
Diameter/Type: 8" steel manhole
Depth BGS: 12" Weep Hole ( Y / (N) )

**Grout**
Composition/Proportions: Portland Type 1/11
4 bags per batch x 3.5 batches = 14 total bags
Placement Method: Tremie Pipe

**Seal** Date: 5-19-21
Type: Bentonite - 1 bag
Source: Hole Plug
Set-up/Hydration Time: >12 hours
Placement Method: Direct Pour
Vol. Fluid Added: N/A

**Filter Pack**
Type: 20/30 Sand
Source: Standard Silica Sand Co.
Amount Used: 10 bags
Placement Method: Direct Pour

**Well Riser Pipe**
Casing Material: PVC
Casing Inside Diameters: 2 in.

**Screen**
Material: PVC
Inside Diameter: 2 in.
Screen Slot Size:: 0.010 in.
Percent Open Area: -
Sump or Bottom Cap ( (Y) / N )
Type/Length: Bottom Cap / 4.5"

**Total Water Volume During Construction**
Introduced (Gal): 650
Recovered (Gal): 165

**Reviewed**
By: _____ Date: _____

**Comments**

3.5 batches of grout as of 5-20-21
15 batches of pea gravel as of 5-20-21
8" drilled to 40' bls for overide casing

# WELL CONSTRUCTION LOG
# STANDARD FLUSH MOUNT

Well I.D.: DEPMW-4 (25-45')
Drilling Company: Preferred Drilling Solutions
Driller(s): Kent Fowler
Geologist/Eng./Tech.: Boone Abbott
Signature: [signature]

Site: Former Florida State Fire College
Project Number: FR75224.01.04
Installation Method: Sonic
Casing Installation Date: 5-20-21
Well Type: Groundwater Monitoring
Well Completion Method: Flush Mount




**Comments**

**Well Completion**
Guard Posts ( Y / (N) ) Date: 5-27-21
Surface Pad Size: 2 ft x 2 ft

**Protective Casing or Cover**
Diameter/Type: 8" steel manhole
Depth BGS: 12" Weep Hole ( Y / (N) )

**Grout**
Composition/Proportions: Portland Type I/II
4 bags per batch x 1 batches = 4 total bags (94lb)
Placement Method: Tremie Pipe

**Seal** Date: 5-20-21
Type: 30/65 Fine Sand - 1 bag
Source: Standard Sand & Silica Co.
Set-up/Hydration Time: -
Placement Method: Direct Pour
Vol. Fluid Added: -

**Filter Pack**
Type: 20/30 Sand
Source: Standard Sand & Silica Co.
Amount Used: 10 bags
Placement Method: Direct Pour

**Well Riser Pipe**
Casing Material: 2" PVC
Casing Inside Diameters: 2 in.

**Screen**
Material: PVC
Inside Diameter: 2 in.
Screen Slot Size:: 0.010 in.
Percent Open Area: -
Sump or Bottom Cap ( (Y) / N )
Type/Length: Bottom Cap / 4.5"

**Total Water Volume During Construction**
Introduced (Gal): 350
Recovered (Gal): 110

**Reviewed**
By: _____ Date: _____

# WELL CONSTRUCTION LOG
# STANDARD FLUSH MOUNT

Well I.D.: DEPMW-5 (100-120')
Drilling Company: Preferred Drilling Solutions
Driller(s): Kent Fowler
Geologist/Eng./Tech.: Boone Abbott
Signature:

Site: Former Florida State Fire College
Project Number: FR7522A.01.04
Installation Method: Sonic
Casing Installation Date: 5-21-21
Well Type: Groundwater Monitoring
Well Completion Method: Flush Mount




**Well Completion**
Guard Posts ( Y / N) Date: 5-27-21
Surface Pad Size: 2 ft x 2 ft

**Protective Casing or Cover**
Diameter/Type: 8" steel manhole
Depth BGS: 12" Weep Hole ( Y / N)

**Grout**
Composition/Proportions: Portland Type I/II
4 bags per batch x 3 batches = 12 total bags
Placement Method: tremie pipe

**Seal** Date: 5-21-21
Type: Bentonite
Source: 1/4" Plug - 1 bag
Set-up/Hydration Time: 1 hour
Placement Method: Direct Pour
Vol. Fluid Added: N/A

**Filter Pack**
Type: 20/30 Sand
Source: Standard Sand & Silica Co.
Amount Used: 12 bags
Placement Method: Direct Pour

**Well Riser Pipe**
Casing Material: PVC
Casing Inside Diameters: 2 in.

**Screen**
Material: PVC
Inside Diameter: 2 in.
Screen Slot Size:: 0.010 in.
Percent Open Area: -
Sump or Bottom Cap (Y / N)
Type/Length: Bottom cap/4.5"

**Total Water Volume During Construction**
Introduced (Gal): 900
Recovered (Gal): 165

**Reviewed**
By: Date:

**Comments**

Override 8" to 90' bls

# WELL CONSTRUCTION LOG
# STANDARD FLUSH MOUNT

Well I.D.: DEPMW-6 (25.-15')
Drilling Company: Preferred Drilling Solutions
Driller(s): Clint Fowler
Geologist/Eng./Tech.: Boone Abbott
Signature:

Site: Former Florida State Fire College
Project Number: FR7522A.01.04
Installation Method: Sonic
Casing Installation Date: 5-24-21
Well Type: Groundwater Monitoring
Well Completion Method: Flush Mount




**Well Completion**
Guard Posts ( Y / (N) ) Date: 5-27-21
Surface Pad Size: 2 ft x 2 ft

**Protective Casing or Cover**
Diameter/Type: 8" steel manhole
Depth BGS: 12" Weep Hole ( Y / (N) )

**Grout**
Composition/Proportions: Portland Type I/II
4 bags per batch x 1 batches = 4 total bags
Placement Method: Tremie Pipe / Direct pour

**Seal** Date: 5-24-21
Type: 30/65 sand
Source: Standard Sand + Silica Co.
Set-up/Hydration Time: N/A
Placement Method: Direct Pour
Vol. Fluid Added: N/A

**Filter Pack**
Type: 20/30 sand
Source: Standard Sand + Silica Co.
Amount Used: 10 bags
Placement Method: Direct Pour

**Well Riser Pipe**
Casing Material: PVC
Casing Inside Diameters: 2 in.

**Screen**
Material: PVC
Inside Diameter: 2 in.
Screen Slot Size:: 0.010 in.
Percent Open Area: -
Sump or Bottom Cap ( (Y) / N )
Type/Length: Bottom Cap / 4.5"

**Total Water Volume During Construction**
Introduced (Gal): 250
Recovered (Gal): 165

**Reviewed**
By: _____ Date: _____

**Comments**

# WELL CONSTRUCTION LOG
# STANDARD FLUSH MOUNT

Well I.D.: DEPMW-7 (100-120')
Drilling Company: Preferred Drilling Solutions
Driller(s): Kent Fowler
Geologist/Eng./Tech.: Boone Abbott
Signature:

Site: Former Florida State Fire College
Project Number: FR7522A.01.04
Installation Method: Sonic
Casing Installation Date: 5-25-21
Well Type: Groundwater Monitoring
Well Completion Method: Flush Mount




**Comments**

**Well Completion**
Guard Posts ( Y / (N) ) Date: 5-27-21
Surface Pad Size: 2 ft x 2 ft

**Protective Casing or Cover**
Diameter/Type: 8" steel manhole
Depth BGS: 12" Weep Hole ( Y / (N) )

**Grout**
Composition/Proportions: Portland Type I/II
4 bags per batch x 3 batches = 12 total bags
Placement Method: Tremie Pipe

**Seal** Date: 5-25-21
Type: Bentonite
Source: Hole Plug
Set-up/Hydration Time: 1 hour
Placement Method: Direct Pour
Vol. Fluid Added: N/A

**Filter Pack**
Type: 20/30 Sand
Source: Standard Sand & Silica Co.
Amount Used: See below
Placement Method: Direct Pour

**Well Riser Pipe**
Casing Material: PVC
Casing Inside Diameters: 2 in.

**Screen**
Material: PVC
Inside Diameter: 2 in.
Screen Slot Size:: 0.010 in.
Percent Open Area: -
Sump or Bottom Cap (Y / N)
Type/Length: Bottom Cap / 0.375'

**Total Water Volume During Construction**
Introduced (Gal): 750
Recovered (Gal): 165

**Reviewed**
By: _____ Date: _____

Void encountered around 115 bls. Pea gravel used - 6.5 pallets used, 5 bags hole plug for seal; 14 20/30 on 5-25-21 + 7 20/30 on 5-26-21 used
a 20 foot section of 4" PVC with a belled end was used to bridge the void from 115-95 ft bls.
5-25-21: 6 pallets of pea gravel, got annular space up to 107 ft bls, came back on 5-26-21, 6" casing fell 10' & took well with it.
PDS pulled casing & well came too. PDS reinstalled well to 120 ft but pea gravel fell back to 115 from 107 the day before, that's why
a 20' section of 4" PVC was used to slide over the 2" well to help bridge it off. PDS cut slots in the 4" to provide more access
for water, then PDS installed 1/2 pallet of pea gravel + 1 bag of fine sand to ensure that it was filled above the 4" PVC before installing the seal, 1 large seal was installed to ensure no grout intrusion since 20 ft was bridged off below

# WELL CONSTRUCTION LOG
# STANDARD FLUSH MOUNT

Well I.D.: DEPMW-8 (20-40')
Drilling Company: Preferred Drilling Company
Driller(s): Kent Fowler
Geologist/Eng./Tech.: Boone Abbott
Signature: [signature]

Site: Former Florida State Fire College
Project Number: FR75224.01.04
Installation Method: Sonic
Casing Installation Date: 5-26-21
Well Type: Groundwater Monitoring
Well Completion Method: Flush Mount




**Comments**

**Well Completion**
Guard Posts ( Y / (N)) Date: 5-27-21
Surface Pad Size: 2 ft x 2 ft

**Protective Casing or Cover**
Diameter/Type: 8" steel manhole
Depth BGS: 12" Weep Hole ( Y / (N))

**Grout**
Composition/Proportions: Portland Type I/II
4 bags per batch x 13 batches = 52 total bags
Placement Method: Tremie Pipe / Direct pour

**Seal** Date: 5-26-21
Type: 30/65 Fine Sand
Source: Standard Sand + Silica Co.
Set-up/Hydration Time: N/A
Placement Method: Direct Pour
Vol. Fluid Added: N/A

**Filter Pack**
Type: 20/30 Sand
Source: Standard Sand + Silica Co.
Amount Used: 13 bags
Placement Method: Direct Pour

**Well Riser Pipe**
Casing Material: PVC
Casing Inside Diameters: 2 in.

**Screen**
Material: PVC
Inside Diameter: 2 in.
Screen Slot Size:: 0.010 in.
Percent Open Area: —
Sump or Bottom Cap (Y / N)
Type/Length: Bottom Cap - 0.375' (0.4')

**Total Water Volume During Construction**
Introduced (Gal): 200
Recovered (Gal): 165

**Reviewed**
By: _____ Date: _____

FLWP/Forms/Field Forms/Well Construction/Well Construction Logs/well construction log-flushA_2016

Geosyntec consultants

# Well Development Log

Site: Former Florida State Fire College — Project No.: FR7522A.01.04

Monitoring Well: DEPMW-1 (100-120') — Date: 5-25-21

Well Condition: Newly Installed — PID (ppm): -

Initial Depth to Water (ft): 31.47 — Initial Depth to Bottom (ft): 120.10

Well Diameter (in): 2" — Height of Water (ft): 88.63

multiply height by 0.163 for 2" well, 0.64 for 4" well = Total Volume in Well (g): ~~120~~ 14.4 gals

Final Depth to Water (ft): 31.47 — Final Depth to Bottom (ft): 120.10

| Time | Flow Rate (gal/min) | Total Volume Removed (gal) | Depth to Water (ft BTOC) | Turbidty (ntu) | pH (SU) | Sp. Cond. (mS/cm) | Temp. (°C) | Dissolved Oxygen (mg/L) | ORP (mV) | Appearance of Water (color, odor) |
|---|---|---|---|---|---|---|---|---|---|---|
| 1756 | ~1.4 | | 31.51 | 23.6 | | | | | | clear |
| 1816 | ~1.4 | | 31.50 | 85.2 | | | | | | cloudy |
| 1820 | 1.4 | | 31.50 | 48.3 | | | | | | cloudy |
| 1821 | 1.4 | | 31.50 | 32.3 | | | | | | cloudy |
| 1823 | 1.4 | | 31.50 | 25.6 | | | | | | cloudy |
| 1825 | 1.4 | | 31.50 | 18.2 | | | | | | clear |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |

Describe Development Method (e.g., pumping, surging, instrumentation total volume removed, rest periods, problems, deviations from plan, etc.)

1630: began pumping - cloudy / white — Submersible pump
1635: surged
1643 surged
1707 surged
1711 surged
1708 - Filled 1 drum
1735 surged
1737 surged
1747 - filled 2 drum
1825 stopped development - 3 drums full + less than 20 NTU — 165 gal removed
pulled out 11.4 well volumes

**Water Quality Meter**

Meter Number: LaMotte 2020 we — 10 = 10.04 NTU

Calibrated on/by: 5-25-21 / BA

**Stabilization Parameters**

3 drums full or <20 NTU

Geosyntec consultants

# Well Development Log

Site: Former Florida State Fire College — Project No.: FR7522A.01.04

Monitoring Well: DEPMW-2(25-45') — Date: 5-26-21

Well Condition: Newly Installed — PID (ppm): -

Initial Depth to Water (ft): 31.97 — Initial Depth to Bottom (ft): 45.00 (before being set for pump)

Well Diameter (in): 2" — Height of Water (ft): 13.06

multiply height by 0.163 for 2" well, 0.64 for 4" well = Total Volume in Well (g): 2.13 gal

Final Depth to Water (ft): 31.98 — Final Depth to Bottom (ft): 45.00

| Time | Flow Rate (gal/min) | Total Volume Removed (gal) | Depth to Water (ft BTOC) | Turbidty (ntu) | pH (SU) | Sp. Cond. (mS/cm) | Temp. (°C) | Dissolved Oxygen (mg/L) | ORP (mV) | Appearance of Water (color, odor) |
|---|---|---|---|---|---|---|---|---|---|---|
| 1119 | 1.6 | | 32.19 | 10.93 | | | | | | clear |
| 1128 | 1.6 | | 32.20 | 9.70 | | | | | | clear |
| 1204 | 1.6 | | 32.20 | 11.73 | | | | | | clear |
| 1236 | 1.6 | | 32.21 | 38.62 | | | | | | cloudy |
| 1244 | 1.6 | | 32.21 | 16.71 | | | | | | clear |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |

Describe Development Method (e.g., pumping, surging, instrumentation total volume removed, rest periods, problems, deviations from plan, etc.)

submersible pump

1102: Begin pumping - cloudy/white
1106 surged
1121 surged
1131 surged
1206 surged
1220 surged - filled 2 drums, moved pump
1245 stopped pumping - filled 3 drums - 165 gal

1150: moved pump up / filled 1 drum

**Water Quality Meter**

Meter Number: LaMotte 2020we 10=10.04.2020

Calibrated on/by: 5-25-21 / DA

**Stabilization Parameters**

3 drums or <20 NTU

Geosyntec consultants

# Well Development Log

Site: Former Florida State Fire College  Project No.: FR 7522A.01.04

Monitoring Well: DFPMW-3(100-120)  Date: 5-26-21

Well Condition: Newly Installed  PID (ppm): -

Initial Depth to Water (ft): 30.02  Initial Depth to Bottom (ft): 119.40

Well Diameter (in): 2  Height of Water (ft): 88.98

multiply height by 0.163 for 2" well, 0.64 for 4" well = Total Volume in Well (g): 14.5

Final Depth to Water (ft): 30.02  Final Depth to Bottom (ft): 119.50

| Time | Flow Rate (gal/min) | Total Volume Removed (gal) | Depth to Water (ft BTOC) | Turbidty (ntu) | pH (SU) | Sp. Cond. (mS/cm) | Temp. (°C) | Dissolved Oxygen (mg/L) | Appearance of Water (color, odor) |
|---|---|---|---|---|---|---|---|---|---|
| 1414 | 1.1 | | 32.36 | 93 | | | | | cloudy |
| 1500 | 1.1 | | 32.37 | 72 | | | | | cloudy |
| 1520 | 1.1 | | 32.37 | 40.5 | | | | | cloudy |
| 1535 | 1.1 | | 32.37 | 33.1 | | | | | cloudy |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |

Describe Development Method (e.g., pumping, surging, instrumentation total volume removed, rest periods, problems, deviations from plan, etc.)

1355: Begin pumping - cloudy/white  Submersible pump
1420: surged
1430 surged
1502 surged
1521 - moved up screen/surged
1534 - filled 2 drums
1536 surged
1551 surged
1603: surged
1620: stopped pumping, filled 3 drums

**Water Quality Meter**

Meter Number: LaMotte 2020we ID: 10.04 NTU

Calibrated on/by: 5-25-21 / BM

**Stabilization Parameters**

3 drums or <20 NTU

Geosyntec consultants

# Well Development Log

Site: Former Florida State Fire College  Project No.: FR7552A.01.04

Monitoring Well: DEPMW-4(25-45')  Date: 5-26-21

Well Condition: Newly Installed  PID (ppm): -

Initial Depth to Water (ft): 30.18  Initial Depth to Bottom (ft): 44.40

Well Diameter (in): 2  Height of Water (ft): 14.22

multiply height by 0.163 for 2" well, 0.64 for 4" well = Total Volume in Well (g): 2.32

Final Depth to Water (ft): 30.17  Final Depth to Bottom (ft): 44.45

| Time | Flow Rate (gal/min) | Total Volume Removed (gal) | Depth to Water (ft BTOC) | Turbidty (ntu) | pH (SU) | Sp. Cond. (mS/cm) | Temp. (°C) | Dissolved Oxygen (mg/L) | ORP (mV) | Appearance of Water (color, odor) |
|---|---|---|---|---|---|---|---|---|---|---|
| 1757 | 1.2 | | 30.31 | 7.26 | | | | | | clear |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |

Describe Development Method (e.g., pumping, surging, instrumentation total volume removed, rest periods, problems, deviations from plan, etc.)

1630: Began pumping - cloudy/white  Submersible pump
1642: surged
1659: surged
1708: surged
1715: surged
1724 surged
1732 surged: filled 1 drum
1737 surged
1742 surged
1750 surged
1800: filled 2 drums, 7.26 NTU, 110 removed

**Water Quality Meter**

Meter Number: Turbidite 2020we 10-10.0 4 NTU

Calibrated on/by: 5-25-21 / BT

**Stabilization Parameters**

3 drums or <20 NTU

Geosyntec consultants

# Well Development Log

Site: Former Florida State Fire College  Project No.: FR7522A.01.04

Monitoring Well: DEPMW-5(100-120')  Date: 5-26-21

Well Condition: Newly Installed  PID (ppm): -

Initial Depth to Water (ft): 31.55  Initial Depth to Bottom (ft): 120.3

Well Diameter (in): 2  Height of Water (ft): 88.75

multiply height by 0.163 for 2" well, 0.64 for 4" well = Total Volume in Well (g): 14.47

Final Depth to Water (ft): 31.57  Final Depth to Bottom (ft): 120.3

| Time | Flow Rate (gal/min) | Total Volume Removed (gal) | Depth to Water (ft BTOC) | Turbidty (ntu) | pH (SU) | Sp. Cond. (mS/cm) | Temp. (°C) | Dissolved Oxygen (mg/L) | Appearance of Water (color, odor) |
|---|---|---|---|---|---|---|---|---|---|
| 2007 | 1.3 | | 31.66 | 38.2 | | | | | cloudy |
| 2014 | 1.3 | | 31.66 | 26.8 | | | | | clear |
| 2018 | 1.3 | | 31.66 | 24.8 | | | | | clear |
| 2021 | 1.3 | | 31.66 | 21.9 | | | | | clear |
| 2028 | 1.3 | | 31.66 | 22.2 | | | | | clear |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |

Describe Development Method (e.g., pumping, surging, instrumentation total volume removed, rest periods, problems, deviations from plan, etc.)

submersible pump

1820: Pumping began, cloudy/white
1832: surged
1849: surged
1855: surged
1913: surged
~~1921: stopped pumping, 3 drums filled~~
1926: surged

2029: Stopped pumping, filled 3 drums

**Water Quality Meter**

Meter Number: LaMotte 2020we ID: 10.21 NTV

Calibrated on/by: 5-26-21 / BM

**Stabilization Parameters**

3 drums or <20 NTV

Geosyntec consultants

# Well Development Log

Site: Former Florida State Fire College  Project No.: FR7522A.01.04

Monitoring Well: DEPMW-6 (25-45')  Date: 5-26-21

Well Condition: Newly Installed  PID (ppm): –

Initial Depth to Water (ft): 31.65  Initial Depth to Bottom (ft): 44.98

Well Diameter (in): 2  Height of Water (ft): 13.33

multiply height by 0.163 for 2" well, 0.64 for 4" well = Total Volume in Well (g): 2.18

Final Depth to Water (ft): 31.66  Final Depth to Bottom (ft): 49.98

| Time | Flow Rate (gal/min) | Total Volume Removed (gal) | Depth to Water (ft BTOC) | Turbidty (ntu) | pH (SU) | Sp. Cond. (mS/cm) | Temp. (°C) | Dissolved Oxygen (mg/L) | Appearance of Water (color, odor) |
|---|---|---|---|---|---|---|---|---|---|
| 1932 | 2.2 | | 31.78 | 5.89 | | | | | clear |
| 1940 | 2.2 | | 31.78 | 3.61 | | | | | clear |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |

Describe Development Method (e.g., pumping, surging, instrumentation total volume removed, rest periods, problems, deviations from plan, etc.)

1830: Pumping began, cloudy white submersible pump
1833: surged
1845: surged
1856: surged
1912: surged
1925: surged
1945: Stopped pumping, filled 3 drums slow NTU

**Water Quality Meter**

Meter Number: LaMotte 2020we 10 = 10.21 NTU

Calibrated on/by: 5-26-21 / DL

**Stabilization Parameters**

3 Drums or 420 NTU

Geosyntec consultants

# Well Development Log

Site: Former FSTC

Project No.: FR7522A.01.04

Monitoring Well: DFPMW-7(100-120') Date: 5.27.21

Well Condition: Newly Installed PID (ppm): -

Initial Depth to Water (ft): 27.61 Initial Depth to Bottom (ft): 119.8

Well Diameter (in): 2 Height of Water (ft): 92.19

multiply height by 0.163 for 2" well, 0.64 for 4" well = Total Volume in Well (g): 15.0

Final Depth to Water (ft): 27.60 Final Depth to Bottom (ft): 119.8

| Time | Flow Rate (gal/min) | Total Volume Removed (gal) | Depth to Water (ft BTOC) | Turbidty (ntu) | pH (SU) | Sp. Cond. (mS/cm) | Temp. (°C) | Dissolved Oxygen (mg/L) | Appearance of Water (color, odor) |
|---|---|---|---|---|---|---|---|---|---|
| 1252 | 1.8 | | 27.63 | 1.87 | | | | | clear |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |

Describe Development Method (e.g., pumping, surging, instrumentation total volume removed, rest periods, problems, deviations from plan, etc.)

1130: Pumping begins, while cloudy submersible pump

1300: Pumping stopped: surged, clear from the start + surged over 10 times, turbidity became clear after surging every time

**Water Quality Meter**

Meter Number: LaMotte 2020 we 10-10.21

Calibrated on/by: 5-26-21 / BA

**Stabilization Parameters**

3 drums or <20 NTU

Geosyntec consultants

# Well Development Log

Site: Former FSFC  Project No.: FN7522A.01.04

Monitoring Well: ~~Former BSB~~ DEPMW-8 (20-40')  Date: 5-27-21

Well Condition: Newly Installed  PID (ppm): –

Initial Depth to Water (ft): 27.69  Initial Depth to Bottom (ft): 39.97

Well Diameter (in): 2  Height of Water (ft): 12.28

multiply height by 0.163 for 2" well, 0.64 for 4" well = Total Volume in Well (g): 2.0

Final Depth to Water (ft): 27.65  Final Depth to Bottom (ft): 39.99

| Time | Flow Rate (gal/min) | Total Volume Removed (gal) | Depth to Water (ft BTOC) | Turbidty (ntu) | pH (SU) | Sp. Cond. (mS/cm) | Temp. (°C) | Dissolved Oxygen (mg/L) | Appearance of Water (color, odor) |
|---|---|---|---|---|---|---|---|---|---|
| 1055 | 1.3 | | 27.65 | 5.42 | | | | | clear |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |

Describe Development Method (e.g., pumping, surging, instrumentation total volume removed, rest periods, problems, deviations from plan, etc.)

0920: Began pumping, while/cloudy
0930 surged
0936 surged
0942 surged
0955 surged
1010 surge 1
1020 surge 1
1030 surge 1
1040 surged
1050 surged
1125: stopped pumping 3 drums full + low NTU

submersible pump

**Water Quality Meter**

Meter Number: Lamotte 2020we 10-1021

Calibrated on/by: 5-26-21 / BA

**Stabilization Parameters**

3 drums or <20 NTU

**Geosyntec Consultants**
**Water Quality Instrument Calibration Form**

Project/Site: Former Florida State Fire College  Project #: FR7522A.01.04  Field Personnel: Boone Abbott

Water Quality Meter - Model/Serial #:  Turbidimeter - Model/Serial # LaMotte 2020we / 1776-0212

| Dissolved Oxygen | DEP SOP FT 1500 | Date | Time | Temp (°C) | Saturation (mg/L)[1] | Reading (mg/L) | Reading (%) | Pass or Fail |
|---|---|---|---|---|---|---|---|---|
| | | | | | | Acceptance Criteria: +/-0.3mg/L | | |
| CAL ICV CCV | | | | | | | | P F |
| CAL ICV CCV | | | | | | | | P F |
| CAL ICV CCV | | | | | | | | P F |
| CAL ICV CCV | | | | | | | | P F |

| Specific Conductance | DEP SOP FT 1200 | Date | Time | Standard (mS/cm) | Standard Lot # | Standard Exp. Date | Reading (mS/cm) | Pass or Fail |
|---|---|---|---|---|---|---|---|---|
| | | | | | | Acceptance Criteria: +/- 5% | | |
| CAL ICV CCV | | | | | | | | P F |
| CAL ICV CCV | | | | | | | | P F |
| CAL ICV CCV | | | | | | | | P F |
| CAL ICV CCV | | | | | | | | P F |

| pH | DEP SOP FT 1100 | Date | Time | Standard (SU) | Standard Lot # | Standard Exp. Date | Reading (SU) | Pass or Fail |
|---|---|---|---|---|---|---|---|---|
| | | | | | | Acceptance Criteria: +/-0.2 SU | | |
| CAL ICV CCV | | | | | | | | P F |
| CAL ICV CCV | | | | | | | | P F |
| CAL ICV CCV | | | | | | | | P F |
| CAL ICV CCV | | | | | | | | P F |
| CAL ICV CCV | | | | | | | | P F |
| CAL ICV CCV | | | | | | | | P F |
| CAL ICV CCV | | | | | | | | P F |
| CAL ICV CCV | | | | | | | | P F |
| CAL ICV CCV | | | | | | | | P F |

| ORP | SOP N/A | Date | Time | Std. mV @ Temp °C | Standard Lot # | Standard Exp. Date | Reading (mV) | Pass or Fail |
|---|---|---|---|---|---|---|---|---|
| | | | | | | Geosyntec Acceptance Criteria: +/- 5% | | |
| CAL ICV CCV | | | | | | | | P F |
| CAL ICV CCV | | | | | | | | P F |
| CAL ICV CCV | | | | | | | | P F |

Specific Conductance Probe Cleaned? Yes No  Disolved Oxygen membrane Changed? Yes No

| 0.1 - 10 NTU Std 10 NTU | Date | Reading (NTU) | Pass or Fail |
|---|---|---|---|
| | | Acceptance Criteria: +/- 10% | |
| CAL (ICV) CCV | 5-25-21 | 10.04 | (P) F |
| CAL ICV (CCV) | 5-26-21 | 10.21 | (P) F |
| CAL ICV CCV | | | P F |
| CAL ICV CCV | | | P F |

| 11 - 40 NTU Std ____NTU | Date | Reading (NTU) | Pass or Fail |
|---|---|---|---|
| | | Acceptance Criteria: +/- 8% | |
| CAL ICV CCV | | | P F |
| CAL ICV CCV | | | P F |
| CAL ICV CCV | | | P F |
| CAL ICV CCV | | | P F |

| 41 - 100 NTU Std ____NTU | Date | Reading (NTU) | Pass or Fail |
|---|---|---|---|
| | | Acceptance Criteria: +/- 6.5% | |
| CAL ICV CCV | | | P F |
| CAL ICV CCV | | | P F |
| CAL ICV CCV | | | P F |
| CAL ICV CCV | | | P F |
| CAL ICV CCV | | | P F |
| CAL ICV CCV | | | P F |
| CAL ICV CCV | | | P F |
| CAL ICV CCV | | | P F |
| CAL ICV CCV | | | P F |

| >100 NTU Std ____NTU | Date | Reading (NTU) | Pass or Fail |
|---|---|---|---|
| | | Acceptance Criteria: +/- 5% | |
| CAL ICV CCV | | | P F |
| CAL ICV CCV | | | P F |
| CAL ICV CCV | | | P F |

1. **See Table FS 2200-2 on the back of this form**

CAL - Initial Calibration
ICV - Initial Calibration Verification
CCV - Continuing Calibration Verification

Comments:

Allow adequate time for the dissolved oxygen sensor to equilibrate during air calibration
Calibrate specific conductance using at least two standards that bracket the range of expected sample readings (unless readings < 0.1 mS/cm then one standard of 0.1 mS/cm is acceptable)
Calibrate pH using at least two standards (typ. pH 4 and 7) that bracket the range of expected sample readings; always start with pH 7; add a third calibration point if needed (i.e. pH > 7)
If parameter fails to calibrate within SOP acceptance criteria then append sample results with a "J" qualifier

Geosyntec consultants

**FIELD DRUM INVENTORY TRACKING LOG**

**Project No.:** FR7522A.01.04 **Project Start Date:** 5-17-21

| Drum Number | Generation Date | Content % Full | Contents (soil, development water, purge water, etc.) | Source Location (Well #, Boring #, etc.) | |
|---|---|---|---|---|---|
| 1 | 5-17-21 - 5-19-21 | 75% | Drill Mud / Decon Water | DEPMW-1+2 | S |
| 2 | 5-21-21 | 100% | Soil | DEPMW-5 | S |
| 3 | 5-21-21 | 30% | Soil | DEPMW-5 | S |
| 4 | 5-21-21 | 100% | Drill Mud | DEPMW-5 | S |
| 5 | 5-18-21 - 5-20-21 | 100% | Soil | DEPMW-3+4 | S |
| 6 | 5-24-21 - 5-26-21 | 80% | Drill Mud | DEPMW-7+8 | S |
| 7 | 5-18-21 - 5-20-21 | 100% | Soil | DEPMW-3+4 | S |
| 8 | 5-18-21 - 5-20-21 | 100% | Drill Mud | DEPMW-3+4 | S |
| 9 | 5-18-21 - 5-19-21 | 80% | Soil | DEPMW-2 | S |
| 10 | [redacted] 5-18-21 | 100% | Soil | DEPMW-1 | S |
| 11 | 5-18-21 | 100% | Soil | DEPMW-1 | S |
| 12 | 5-25-21 | 100% | Development Water | DEPMW-1 | |
| 13 | 5-26-21 | 100% | Development Water | DEPMW-3 | |
| 14 | 5-25-21 | 30% | Drill Mud | DEPMW-6 | S |
| 15 | [redacted] 5-26-21 | 100% | Development Water | DEPMW-6 | |
| 16 | 5-26-21 | 100% | Development Water | DEPMW-6 | |
| 17 | 5-26-21 | 100% | Development Water | DEPMW-5 | |
| 18 | 5-25-21 - 5-26-21 | 80% | Drill Mud | DEPMW-7+8 | S |
| 19 | 5-25-21 | 100% | Decon Water | DEPMW-6 - Decon Pit | |
| 20 | 5-25-21 | 100% | Decon Water | DEPMW-5+6 - Decon Pit | |
| 21 | 5-17-21 - 5-20-21 | 100% | Decon Water | DEPMW-1,2,3,4 | |
| 22 | 5-19-21 - 5-20-21 | 100% | Decon Water | DEPMW 3+4 | |
| 23 | 5-25-21 - 5-26-21 | 80% | Drill Mud | DEPMW-7+8 | S |

**FIELD DRUM INVENTORY TRACKING LOG**

**Project No.:** FR7522A.01.04 **Project Start Date:** 5-17-21

| Drum Number | Generation Date | Content % Full | Contents (soil, development water, purge water, etc.) | Source Location (Well #, Boring #, etc.) | |
|---|---|---|---|---|---|
| 24 | 5-26-21 | 100% | Development Water | DEPMW-6 | |
| 25 | 5-26-21 | 100% | Development Water | DEPMW-5 | |
| 26 | 5-26-21 | 100% | Development Water | DEPMW-5 | |
| 27 | 5-19-21-5-20-21 | 40% | Drill Mud | DEPMW-3+4 | S |
| 28 | 5-19-21-5-20-21 | 100% | Drill Mud | DEPMW-3+4 | S |
| 29 | 5-26-21 | 100% | Development Water | DEPMW-4 | |
| 30 | 5-26-21 | 100% | Development Water | DEPMW-3 | |
| 31 | 5-26-21 | 100% | Development Water | DEPMW-4 | |
| 32 | 5-26-21 | 100% | Development Water | DEPMW-3 | |
| 33 | 5-25-21 | 100% | Development Water | DEPMW-1 | |
| 34 | 5-25-21 | 100% | Development Water | DEPMW-1 | |
| 35 | 5-26-21 | 100% | Development Water | DEPMW-2 | |
| 36 | 5-26-21 | 100% | Development Water | DEPMW-2 | |
| 37 | 5-26-21 | 100% | Development Water | DEPMW-2 | |
| 38 | 5-27-21 | 100% | Development Water | DEPMW-7 | |
| 39 | 5-27-21 | 100% | Development Water | DEPMW-8 | |
| 40 | 5-27-21 | 100% | Development Water | DEPMW-8 | |
| 41 | 5-27-21 | 100% | Development Water | DEPMW-7 | |
| 42 | 5-27-21 | 100% | Development Water | DEPMW-8 | |
| 43 | 5-27-21 | 100% | Development Water | DEPMW-7 | |
| 44 | 5-25-21 | 100% | Soil | DEPMW-7 | S |
| 45 | 5-25-21 | 50% | Soil | DEPMW-7 | S |
| 46 | 5-25-21 | 75% | Soil/Drill Mud | DEPMW-7 | S |

**FIELD DRUM INVENTORY TRACKING LOG**

**Project No.:** PR7522A.01.04 **Project Start Date:** 5-17-21

| Drum Number | Generation Date | Content % Full | Contents (soil, development water, purge water, etc.) | Source Location (Well #, Boring #, etc.) |
|---|---|---|---|---|
| 47 | 5-26-21 | 100% | Decon Water | DEPMW-7+8 - Decon Pit |
| 48 | 5-27-21 | 100% | Decon Mud / Fluids | DEPMW-5-8 - Decon Pit |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |

S

* 2 drums added (empty) = 50 total from PDS, these will be used for GW sampling

# ATTACHMENT B

Photographic Log

# GEOSYNTEC CONSULTANTS
## Photographic Record

| | |
|---|---|
| **Client: Florida Department of Environmental Protection** | **Project Number: FR7522A** |
| **Site Name: Former Florida State Fire College (FFSFC)** | **Site Location: 1501 W Silver Springs Blvd, Ocala, FL** |

| | |
|---|---|
| **Photograph 1** |  |
| **Date: 17 May 2021 9:17 AM** | |
| **Direction: W** | |
| **Comments: Utility locating was performed prior to subsurface activities.** | |

| | |
|---|---|
| **Photograph 2** |  |
| **Date: 18 May 2021 11:38 AM** | |
| **Direction: N** | |
| **Comments: View of the drilling decontamination pit. All rods and casing were decontaminated prior to work and after each soil boring using per- and polyfluoroalkyl substance-free water. Equipment blanks were collected from decontaminated tooling.** | |

# GEOSYNTEC CONSULTANTS
## Photographic Record

Geosyntec consultants

| | |
|---|---|
| **Client: Florida Department of Environmental Protection** | **Project Number: FR7522A** |
| **Site Name: Former Florida State Fire College (FFSFC)** | **Site Location: 1501 W Silver Springs Blvd, Ocala, FL** |

| | |
|---|---|
| **Photograph 3** |  |
| **Date: 19 May 2021 8:41 AM** | |
| **Direction: S** | |
| **Comments: Eight monitoring wells were installed via rotosonic drilling across the site. A water-table monitoring well and a deep monitoring well were paired at 4 locations.** | |

| | |
|---|---|
| **Photograph 4** |  |
| **Date: 18 May 2021 9:27 AM** | |
| **Direction: NA** | |
| **Comments: Soil cores were collected from 5 feet below land surface to a total depth of 120 ft at each well pair location.** | |

| GEOSYNTEC CONSULTANTS<br>Photographic Record | Geosyntec consultants |
|---|---|
| **Client: Florida Department of Environmental Protection** | **Project Number: FR7522A** |
| **Site Name: Former Florida State Fire College (FFSFC)** | **Site Location: 1501 W Silver Springs Blvd, Ocala, FL** |

| | |
|---|---|
| **Photograph 5**<br>**Date: 27 May 2021 12:46 PM**<br>**Direction: S**<br>**Comments: Wells were completed flush to grade and set in an 8-inch diameter manhole set in a 2 ft x 2 ft concrete well pad.** |  |
| **Photograph 6**<br>**Date: 27 May 2021 1:09 PM**<br>**Direction: E**<br>**Comments: Monitoring wells were developed by surging and pumping until 3 drums were filled or the turbidity stabilized below 20 NTUs.** |  |

## GEOSYNTEC CONSULTANTS
## Photographic Record

| | |
|---|---|
| **Client: Florida Department of Environmental Protection** | **Project Number: FR7522A** |
| **Site Name: Former Florida State Fire College (FFSFC)** | **Site Location: 1501 W Silver Springs Blvd, Ocala, FL** |

| | |
|---|---|
| **Photograph 7** |  |
| **Date: 27 May 2021 2:56 PM** | |
| **Direction: E** | |
| **Comments: Forty-eight drums containing soil cuttings, decontamination water, drilling mud, and development water were staged at the site.** | |

| | |
|---|---|
| **Photograph 8** |  |
| **Date: 27 May 2021 5:05 PM** | |
| **Direction: E** | |
| **Comments: All forty-eight drums were removed immediately following the event by the waste hauler.** | |

# ATTACHMENT C

Non-Hazardous Waste Manifest

| NON-HAZARDOUS WASTE MANIFEST | 1. Generator ID Number | 2. Page 1 of | 3. Emergency Response Phone | 4. Waste Tracking Number |
|---|---|---|---|---|
| | | | | |

**GENERATOR**

5. Generator's Name and Mailing Address: FDEP, 2600 Blair Stone Rd, Tallahassee, FL 32399
Generator's Phone: (850) 245-8700

Generator's Site Address (if different than mailing address): Former Florida State Fire College, 1501 W. Silver Springs Blvd., Ocala, FL 24475

6. Transporter 1 Company Name: Erwin Remediation, Inc.
U.S. EPA ID Number: FLR000223867

7. Transporter 2 Company Name:
U.S. EPA ID Number:

8. Designated Facility Name and Site Address: Ecosouth Services, 12950-A Highway 43, Axis, AL 36505
Facility's Phone:
U.S. EPA ID Number:

| | 9. Waste Shipping Name and Description | 10. Containers No. | 10. Containers Type | 11. Total Quantity | 12. Unit Wt./Vol. | |
|---|---|---|---|---|---|---|
| 1. | Non-Hazardous Soil/Mud | 20 | DM | | | |
| 2. | Non-Hazardous Water | 28 | DM | | | |
| 3. | | | | | | |
| 4. | | | | | | |

13. Special Handling Instructions and Additional Information

**14. GENERATOR'S/OFFEROR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and governmental regulations.

Generator's/Offeror's Printed/Typed Name: Boone Abbott (as agent of FDEP)
Signature:
Month: 5 Day: 27 Year: 21

**INT'L**

15. International Shipments ☐ Import to U.S. ☐ Export from U.S.
Port of Entry/Exit:
Transporter Signature (for exports only):
Date Leaving U.S.:

**TRANSPORTER**

16. Transport Acknowledgement of Receipt of Materials

Transporter 1 Printed/Typed Name: Tyler Mardf
Signature: T. Mardf
Month: 5 Day: 27 Year: 21

Transporter 2 Printed/Typed Name:
Signature:
Month: Day: Year:

**DESIGNATED FACILITY**

17. Discrepancy

17a. Discrepancy Indication Space ☐ Quantity ☐ Type ☐ Residue ☐ Partial Rejection ☐ Full Rejection

Manifest Reference Number:

17b. Alternate Facility (or Generator)
U.S. EPA IS Number
Facility's Phone:

17c. Signature of Alternate Facility (or Generator)
Month: Day: Year:

18. Designated Facility Owner or Operator: Certification of receipt of materials covered by the manifest except as noted in item 17a

Printed/Typed Name:
Signature:
Month: Day: Year: