



Figure 10
Summary of Analytical Results in Soil
Palm Beach State College
4200 South Congress Avenue
Lake Worth, Palm Beach County, Florida

- Notes:**
1. Results and screening criteria are presented in micrograms per kilogram ($\mu\text{g}/\text{Kg}$).
 2. I indicates result is between the laboratory method detection limit (MDL) and the laboratory practical quantitation limit.
 3. J indicates estimated value and/or the analysis did not meet the quality control criteria.
 4. U indicates material was analyzed for but not detected. The reported value is the MDL for the sample analyzed.
 5. Depth is presented in feet (ft) below land surface (BLS).
 6. Gray shaded, bold text indicates an exceedance of the Florida Department of Environmental Protection provisional leachability soil cleanup target level (SCTL).
 7. ** indicates saturated soil sample; results not compared to FDEP provisional SCTL. See Table 4 for depth to water measurements collected in monitoring wells.
 8. AFFF indicates aqueous film forming foam.
 9. Approximate parcel boundaries downloaded from Palm Beach Property Appraiser (file dated 12 March 2019).
 10. Source of 2019 World Imagery: Esri, DigitalGlobe, GeoEye, Earthstar Geographics, CNES/Airbus DS, USDA, USGS, AeroGRID, IGN, and the GIS User Community



100
 Feet



Date: May 14, 2020