

TIMELINE OF ACTIVITIES CHIPOLA COLLEGE FIRE TRAINING FACILITY

DATE	ACTIONS	Program or Agency Involved	NOTES
1/10/19	Facility Outreach	DEP	To inform of the ongoing assessment effort, coordinate site access and answer questions. DEP Site Number: ERIC_7393
1/15/19	DEP performs site visit and sample collection at Chipola College Fire Training Facility.	DEP	Samples collected from facility's supply well and a water fountain. The facility relies on bottled water for drinking.
1/31/19	Certified Chipola Sampling Results Received.	DEP	SIS-2019-01-15-01 laboratory report certified. All samples were non-detect. DEP plans to conduct additional soil and groundwater sampling.
2/18/19 and 2/19/19	DEP collected soil and groundwater samples as well as a surface water sample from the fire suppression pond.	DEP	Samples were sent to DEP's certified lab in Tallahassee.
3/21/19	Certified Sampling Results Received, and data shared with Chipola Fire Training Facility.	DEP	SIS-2019-02-19-01 laboratory report certified. Results of the additional soil and groundwater sampling did not exceed cleanup target levels. No additional work is needed.